

[Upgrade to Revision]

R20TS1012EJ0100

Rev.1.00

CS+ Device Information for RL78 V8.11.01

Apr. 16, 2024

Outline

CS+ for CC Device Information for RL78 has been updated from V8.11.00 to V8.11.01.

CS+ for CA, CX Device Information for RL78 has been updated from V8.10.02 to V8.11.01.

1. Items to Be Updated

- CS+ for CC Device Information for RL78 V3.00.00 or later
- CS+ for CA, CX Device Information for RL78 V3.00.00 or later
- CubeSuite+ DevInfo_RL78_78K V1.00.18 or earlier

To check the versions of the items above, visit the web page below and follow the steps in [Components].

<https://www.renesas.com/cs+ ver>

2. Description

The following section covers the main update. For details, see the web page below.

(The information is applicable as of April 22.)

https://www.renesas.com/cs+/eng/CSPlus_DevInfo_RL78.html

2.1 Correction of Device Information

The device information of the following group has been corrected.

- RL78/G15 group
- RL78/G16 group
- RL78/G23 group
- RL78/FGIC

2.2 Addition of Supported Devices

Supported devices of the following group has been added.

- RL78/G15 group
- RL78/G23 group

3. Updating the Product

3.1 CS+ V3.00.00 or Later

Update in either of the following ways.

- (1) Open the Windows Start menu, select [Programs], [Renesas Electronics CS+], and then run Update Manager. (The service is available as of April 22.)

Note: If you have started CS+ with the Rapid Startup function enabled, exit CS+, and then run Update Manager.

If the Rapid Startup function is enabled and CS+ is shown in the Windows notification area, the following error message appears.

M0120001

"CubeSuiteW+.exe"

Installation is suspended because "CubeSuiteW+.exe" is running.

It will be resumed next time you start the tool.

- (2) Download and install the desired software tool from the link below.

(Tools are available as of April 22.)

<https://www.renesas.com/us/en/software-tool/cs#download>

3.2 CubeSuite+ V2.00.00 to V2.02.00

See 3.1 and update in the same way.

3.3 CubeSuite+ V1.03.00 or Earlier

Update Manager does not support CubeSuite+ V1.03.00 and earlier.

Download and install CS+ for CC V8.11.00 or CS+ for CA, CX V4.08.00 from the link below, and then update the program as shown in 3.1 above.

<https://www.renesas.com/us/en/software-tool/cs#download>

Revision History

Rev.	Date	Description	
		Page	Summary
1.00	Apr.16.24	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URLs in the Tool News also may be subject to change or become invalid without prior notice.

Corporate Headquarters

TOYOSU FORESIA, 3-2-24 Toyosu,
Koto-ku, Tokyo 135-0061, Japan
www.renesas.com

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

Contact Information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit:
www.renesas.com/contact/