

RENESAS TECHNICAL UPDATE

1753, Shimonumabe, Nakahara-ku, Kawasaki-shi, Kanagawa 211-8668 Japan
Renesas Electronics Corporation

Product Category	MPU/MCU		Document No.	TN-SH7-A800A/E	Rev.	1.00
Title	Permanent measures about SH7216 watch dog timer issue		Information Category	Technical Notification		
Applicable Product	SH7216 Group SH7214 Group	Lot No.	Reference Document	Notes on Usage of the Watchdog Timer in SH7216 Products (TN-SH7-A770A/E) SH7214 Group,SH7216 Group User's manual:Hardware (REJ09B0543-0200)		
		Week code After 1045				

The issue of the watch dog timer was reported by technical update TN-SH7-A770A/E. And permanent measure has been completed and is reported as followings.

Note

It can be confirmed that it is a week code or an interior label.

1. mass-produced since November, 2010 (after Week code 1045)
2. The end of the type name of interior label SPN is V1 or U1.

Package

Label example

PLQP0176LA-B

S.LOT	BF07974K		
D/N	R5F72167WADFAU		
TQTY	20	QTY	20
SPN	R5F72167ADFA#V1		
SPL	10290Y101G		

PLQP0176KB-A

S.LOT	BF07974K2		
D/N	R5F72167WADFPU		
TQTY	37	QTY	37
SPN	R5F72167ADFP#V1		
SPL	10280Y1003		

PLBG0176GA-A

S.LOT	BL06155K		
D/N	R5F72167WADBGV		
TQTY	65	QTY	65
SPN	R5F72167ADBG#U1		
SPL	11030Y100B		