# [Upgrade to Revision] e<sup>2</sup> studio RL78 Smart Configurator Plug-in V1.6.0 Smart Configurator for RL78 V1.6.0

R20TS0939EJ0100 Rev.1.00 Apr. 16, 2023

#### Outline

The products in the title have been updated as follows.

- (1) e<sup>2</sup> studio RL78 Smart Configurator Plug-in: From V1.5.0 to V1.6.0
- (2) Smart Configurator for RL78: From V1.5.0 to V1.6.0

### 1. Products to Be Updated

- ▶ e<sup>2</sup> studio 2023-01 (Smart Configurator Plug-in V1.5.0)
- Smart Configurator for RL78 V1.5.0

# 2. Description

The following issue has been fixed.

- 1. Fixed the issue of XT1 oscillator can be selected when the low-speed on-chip oscillator is running.
- 2. Fixed the issue of the redundant contents in "Show view" dialog in Standalone Smart Configurator.

For other fixes, please refer to the release notes above.

Smart Configurator for RL78
Smart Configurator for RL78 V1.6.0 Release Note (the note will be uploaded on April 20)
https://www.renesas.com/software-tool/rl78-smart-configurator#documents



# 3. Updating the Product

Refer to the following and update accordingly. The products can be updated free of charge.

#### 3.1 e<sup>2</sup> studio

Refer to the Tool News (3. Updating the Product) at the URL below (the news will be uploaded on April 20).

https://www.renesas.com/software-tool/e-studio#documents

RENESAS TOOL NEWS: R20TS0927EJ0100 (April 16, 2023, issue)

[Upgrade to Version] e<sup>2</sup> studio Integrated Development Environment 2023-04

Note: The Smart Configurator is updated automatically when e<sup>2</sup> studio is updated.

#### 3.2 CS+

Download the latest Smart Configurator for RL78 from the URL below and install it (V1.5.0 will be released on April 20).

https://www.renesas.com/software-tool/smart-configurator#download

Smart Configurator for RL78 V1.6.0

# **Revision History**

		Description	
Rev.	Date	Page	Summary
1.00	Apr.16.23	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URLs in the Tool News also may be subject to change or become invalid without prior notice.

#### **Corporate Headquarters**

TOYOSU FORESIA, 3-2-24 Toyosu, Koto-ku, Tokyo 135-0061, Japan www.renesas.com

#### **Trademarks**

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

## **Contact Information**

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit: <a href="https://www.renesas.com/contact/">www.renesas.com/contact/</a>

© 2023 Renesas Electronics Corporation. All rights reserved.

TS Colophon 4.3