RENESAS TECHNICAL UPDATE

TOYOSU FORESIA, 3-2-24, Toyosu, Koto-ku, Tokyo 135-0061, Japan Renesas Electronics Corporation

| Product Category | MPU/MCU | | Document No. | TN-R8C-A0065A/E | Rev. | 1.00 | |
|---|-----------------------|---------|-------------------------|------------------------|------|------|--|
| Title | R8C Technical inquiry | | Information Category | Technical Notification | | | |
| | | Lot No. | | | | | |
| Applicable Product | R8C Family | All | Reference Document | | | | |
| Since the R8C family products are Non-Promotion (NRND: Not Recommended for New Design) and are not displayed in the product information TOP of "Renesas Electronics Web", we are continuously receiving technical inquiries of the same type. | | | | | | | |
| (A/D conversion accuracy countermeasures, Timers, Serial interface control methods and other notes for using internal function circuits, inquiries about clock switching, register settings, ID code setting usage procedures, etc.) | | | | | | | |
| Therefore, please check the FAQ according to the following procedure to solve problems and unclear points when using. (FAQ about R8C family is classified as "Other MCUs & MPUs ", so please search by the following procedure.) | | | | | | | |
| (Information as of 2021/12) | | | | | | | |
| "Renesas Electronics Web" : https://www.renesas.com/ | | | | | | | |
| Select "Other MCUs & MPUs" in the "PRODUCTS" | | | | | | | |
| Select "R8C Family" | | | | | | | |
| Select "R8C Family FAQ" in the "Support" column | | | | | | | |
| If you cannot solve the problem, please also use "General Support" in the "Support" column. | | | | | | | |
| When designing a new product, please consider the RL78 family, RA family, RX family, etc. | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |

