[Upgrade to revision]

R20TS0659EJ0100 Rev.1.00 Jan. 16, 2021

CS+ Code Generator for RL78 (CS+ for CC) V2.21.00,

CS+ Code Generator for RL78 (CS+ for CA,CX) V2.21.00,

e² studio Code Generator Plug-in V2.18.0,

AP4 Coding Assistance Tool for RL78 V1.20.00,

Applilet3 Coding Assistance Tool for RL78 V1.20.00

Overview

The products in the title will be revised and their version numbers will be changed as follows:

- (1) CS+ Code Generator for RL78 (CS+ for CC): V2.20.00 to V2.21.00
- (2) CS+ Code Generator for RL78 (CS+ for CA,CX): V2.20.00 to V2.21.00
- (3) e² studio Code Generator plug-in: V2.17.0 to V2.18.0
- (4) AP4 Coding Assistance Tool for RL78: V1.18.00 to V1.20.00
- (5) Applilet3 Coding Assistance Tool for RL78: V1.18.00 to V1.20.00

1. Version to Be Updated

- All revisions up to V2.20.00 of CS+ Code Generator for RL78 (CS+ for CC)
- All revisions up to V2.20.00 of CS+ Code Generator for RL78 (CS+ for CA,CX)
- All revisions up to 2020-10 of e² studio (V2.17.0 of Code Generator plug-in)
- All revisions up to V1.18.00 of AP4 Coding Assistance Tool for RL78
- All revisions up to V1.18.00 of Applilet3 Coding Assistance Tool for RL78

2. Items Revised

The major revision points are as follows. Refer to the following release note for details.

Code Generator for RL78 CS+ Code Generator for RL78 (CS+ for CC/CA,CX) V2.21, e² studio Code Generator Plug-in, V2.18.0, AP4 for RL78 V1.20.00, Applilet3 for RL78 V1.20.00 Release Note. This information will be released on January 20.

https://www.renesas.com/software-tool/code-generator-plug#documents

Page 2 of 3

2.1 **Description of Modification**

The problem regarding the point below has been fixed.

(1) RENESAS TOOL NEWS, Document No. R20TS0571EJ0100

1. User option byte (000C1H/010C1H) LVD off setting values

Applicable devices: RL78/G13A group

For details about the problem, refer to the following URL:

https://www.renesas.com/document/tnn/notes-cs-code-generator-rI78-e-studio-code-generator-plugapplilet3-coding-assistance-tool-rl78-0

3. How to Update Your Copy

Online updating is available free of charge. The method of updating depends on the version of your IDE.

For CS+ Code Generator for RL78

For the method of updating CS+ online, refer to section 4, "How to Update Your Copy" in the following Tool News. This information will be released on January 20.

https://www.renesas.com/software-tool/cs#documents

RENESAS TOOL NEWS, January 16, Document No. R20TS0648E0100

[Upgrade to revision] CS+ Integrated Development Environment V8.05.00

For e² studio Code Generator Plug-in 3.2

For the method of updating e² studio, refer to section 3, "Updating Your Product" in the following Tool News. This information will be released on January 20.

https://www.renesas.com/software-tool/e-studio#documents

RENESAS TOOL NEWS, January 16, Document No. R20TS0643E0100

[Upgrade to version] e² studio Integrated Development Environment 2021-01

Note that by updating e² studio, the Smart Configurator will also be updated.

3.3 For AP4 and Applilet3 Coding Assistance Tool for RL78

Download the installer from the following URL, and then install the program. The programs will be available on January 20.

https://www.renesas.com/applilet



Revision History

		Description	
Rev.	Date	Page	Summary
1.00	Jan.16.21	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URL in the Tool News also may be subject to change or become invalid without prior notice.

Corporate Headquarters

TOYOSU FORESIA, 3- 2- 24 Toyosu, Koto-ku, Tokyo 135- 0061, Japan www.renesas.com

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

Contact information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit: www.renesas.com/contact/

© 2021 Renesas Electronics Corporation. All rights reserved.

TS Colophon 4.2