


Vcc-Icc (Wait Mode)

Condition1: CPU Clock=sub, Division Ratio=1/1, Xin Drive Capacity=high, Xcin Drive Capacity=high, Pheripheral Function=no operation, Software Wait=0wait



Caution! This Data is not guaranteed Value.