# [Notes] Smart Configurator for RZ

R20TS0520ES0100 Rev.1.00 Dec. 16, 2019

## Outline

When using Smart Configurator for RZ, note the following point.

- 1. "Camera Serial Interface" and "SPI Multi I/O Bus Controller" peripherals in the Pin Function tab are incorrectly labelled.
- "Camera Serial Interface" and "SPI Multi I/O Bus Controller" Peripherals in the Pin Function Tab are Incorrectly Labelled
- 1.1 Applicable Products
  - Smart Configurator for RZ V1.5.0 or later
- 1.2 Applicable Devices
  - RZ family: RZ/G2E group


## 1.3 Details

In the Hardware Resource panel in the Pin Function tab of the Pins page, the following peripheral names are incorrectly labelled. Note that this issue has no effect on the generated file.

(1) Incorrect label for [Camera Serial Interface]

The peripheral name of CSI0 pins is incorrectly labelled.

Incorrect label: Clock Frequency Control
Correct label: Camera Serial Interface




## (2) Incorrect label for [SPI Multi I/O Bus Controller]

The peripheral names of "RPC\_INIT#" and "RPC\_RESET#" are incorrectly labelled.

Incorrect label: Receive Padding Configuration

Correct label: SPI Multi I/O Bus Controller



## 1.4 Workaround

Read the peripheral name "Clock Frequency Control" and "Receive Padding Configuration" displayed in the Hardware Resource panel as "Camera Serial Interface" and "SPI Multi I/O Bus Controller" respectively.

#### 1.5 Schedule for Fixing the Problem

This problem will be fixed in the next version.

R20TS0520ES0100 Rev.1.00 Dec.16.19

# **Revision History**

		Description	
Rev.	Date	Page	Summary
1.00	Dec.16.19	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

URLs in Tool News also may be subject to change or become invalid without prior notice.

# Corporate Headquarters

TOYOSU FORESIA, 3-2-24 Toyosu, Koto-ku, Tokyo 135-0061 Japan www.renesas.com

## **Trademarks**

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

# Contact information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit: <a href="https://www.renesas.com/contact/">www.renesas.com/contact/</a>

 $\ensuremath{\texttt{©}}$  2019. Renesas Electronics Corporation. All rights reserved.

TS Colophon 4.0