[Upgrade to Revision] e² studio Smart Configurator Plug-in V2.15.0, Smart Configurator for RX V2.15.0

R20TS0885EJ0100 Rev.1.00 Oct. 16, 2022

Outline

The products in the title have been updated as follows.

- (1) e² studio Smart Configurator Plug-in: From V2.14.0 to V2.15.0
- (2) Smart Configurator for RX: From V2.14.0 to V2.15.0

1. Products to Be Updated

- → e² studio 2022-07 (Smart Configurator Plug-in V2.14.0) and earlier
- Smart Configurator for RX V2.14.0 and earlier

2. Description

The main changes are as follows. Refer to the release note in the link below for details.

- Fixed the wrong ISR name issue for Motor component with GCC compiler
- Fixed the r config include path issue when BSP is disabled
- Fixed the S12AD interrupt enable issue for Motor component

Smart Configurator for RX

Smart Configurator for RX V2.15.0 Release Note (The note will be uploaded on October 20th, 2022.) https://www.renesas.com/software-tool/rx-smart-configurator



3. Updating the Product

3.1 e² studio

Refer to the following tool news (section 3, Updating the Product) in the link below. (The news will be uploaded on October 20th, 2022.)

https://www.renesas.com/software-tool/e-studio

RENESAS TOOL NEWS: R20TS0880EJ0100

[Upgrade to Version] e² studio Integrated Development Environment 2022-10

Note: The Smart Configurator is updated when the e^2 studio is updated.

3.2 CS+

Download the Smart Configurator for RX from the link below and install it. (It will be uploaded on October 20th, 2022.)

https://www.renesas.com/smart-configurator#downloads

Smart Configurator for RX V2.15.0

Revision History

		Description	
Rev.	Date	Page	Summary
1.00	Oct.16.22	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URLs in the Tool News also may be subject to change or become invalid without prior notice.

Corporate Headquarters

TOYOSU FORESIA, 3-2-24 Toyosu, Koto-ku, Tokyo 135-0061, Japan

www.renesas.com Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

Contact information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit: www.renesas.com/contact/

© 2022 Renesas Electronics Corporation. All rights reserved.

TS Colophon 4.3