



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

PDN #: <u>SR-08-03R1</u>	Last Buy Deadline for Submission of Order: <u>24-Jul-2009</u>
Issue Date: <u>19-Sep-2008</u>	Last Eligible Ship Date: <u>23-Oct-2009</u>

Contact: Gary Connor
 Title: Marketing Manager - Standard Products
 Phone #: 1-408-284-8495
 Fax #: 1-408-284-1419
 E-mail: Gary.Connor@idt.com

PRODUCT(S) AFFECTED: _____ **ATTACHMENT** Yes No
(List Replacement Part #(s), if any)

Revision 1: This revision is to add additional part numbers into the product discontinuance list, which have been inadvertently missed out in the original PDN notice. The last buy deadline for submission of order and last eligible ship date remain unchanged.

Please see Attachment I for the complete discontinued part number and the recommended replacement part number list. The added part numbers are listed in the last page of Attachment I.

REASON FOR DISCONTINUANCE:

Replace slower speed with faster speed offerings Other: _____
 Obsolete Fab Technology / Process _____
 Obsolete Assembly Technology / Process _____
 Obsolete Package / Material _____
 Declined Market

CUSTOMER NOTIFICATION:

As a result of discontinuance reason(s) listed above, IDT has decided to discontinue certain products and notify you through this Product Discontinuance Notice (PDN). We recommend you to check detailed specifications before converting to equivalent devices offered. Please use acknowledgement below or E-Mail to request additional information.

Last time buy orders may be submitted any time prior to the date indicated above. All orders shall be subject to acceptance by IDT at its sole discretion unless otherwise agreed by IDT in writing.

If you have any questions, please feel free to contact your local IDT distributor or sales representative.

Customer: _____	E-Mail Address: _____
Name/Date: _____	Phone#: _____
Title: _____	Fax#: _____

CUSTOMER COMMENTS: _____

IDT ACKNOWLEDGEMENT:

Received By: _____ Date: _____



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: SR-08-03R1

Discontinued Part#	Recommended Replacement Part#	Discontinued Part#	Recommended Replacement Part#
IDT71P73604S167BQ	None	IDT71T75702S80BG8	None
IDT71P73604S167BQ8	None	IDT71T75702S80BGI	None
IDT71P73604S200BQ	None	IDT71T75702S80BGI8	None
IDT71P73604S200BQ8	None	IDT71T75702S80PF	None
IDT71P73604S250BQ	None	IDT71T75702S80PF8	None
IDT71P73604S250BQ8	None	IDT71T75702S80PFG	None
IDT71P73804S167BQ	None	IDT71T75702S80PFG8	None
IDT71P73804S167BQ8	None	IDT71T75702S80PFGI	None
IDT71P73804S200BQ	None	IDT71T75702S80PFGI8	None
IDT71P73804S200BQ8	None	IDT71T75702S80PFI	None
IDT71P73804S250BQ	None	IDT71T75702S80PFI8	None
IDT71P73804S250BQ8	None	IDT71T75702S85BG	None
IDT71P79604S167BQI	None	IDT71T75702S85BG8	None
IDT71P79604S167BQI8	None	IDT71T75702S85BGI	None
IDT71P79604S250BQ	None	IDT71T75702S85BGI8	None
IDT71P79604S250BQ8	None	IDT71T75702S85PF	None
IDT71P79604S250BQI	None	IDT71T75702S85PF8	None
IDT71P79604S250BQI8	None	IDT71T75702S85PFG	None
IDT71T016SA12BF	None	IDT71T75702S85PFG8	None
IDT71T016SA12BF8	None	IDT71T75702S85PFGI	None
IDT71T016SA12BFI	None	IDT71T75702S85PFGI8	None
IDT71T016SA12BFI8	None	IDT71T75702S85PFI	None
IDT71T016SA15BF	None	IDT71T75702S85PFI8	None
IDT71T016SA15BF8	None	IDT71V016SA10YGI	None
IDT71T016SA15BFI	None	IDT71V016SA10YGI8	None
IDT71T016SA15BFI8	None	IDT71V016SA10YI	None
IDT71T016SA20BF	None	IDT71V016SA10YI8	None
IDT71T016SA20BF8	None	IDT71V2546S100BQ	None
IDT71T016SA20BFI	None	IDT71V2546S100BQ8	None
IDT71T016SA20BFI8	None	IDT71V2546S100BQI	None
IDT71T75702S75BG	None	IDT71V2546S100BQI8	None
IDT71T75702S75BG8	None	IDT71V2546S133BQ	None
IDT71T75702S75BGI	None	IDT71V2546S133BQ8	None
IDT71T75702S75BGI8	None	IDT71V2546S133BQI	None
IDT71T75702S75PF	None	IDT71V2546S133BQI8	None
IDT71T75702S75PF8	None	IDT71V2546S150BQ	None
IDT71T75702S75PFG	None	IDT71V2546S150BQ8	None
IDT71T75702S75PFG8	None	IDT71V2546SA100BG	IDT71V2546S100BG
IDT71T75702S75PFGI	None	IDT71V2546SA100BG8	IDT71V2546S100BG8
IDT71T75702S75PFGI8	None	IDT71V2546SA100BGI	IDT71V2546S100BGI
IDT71T75702S75PFI	None	IDT71V2546SA100BGI8	IDT71V2546S100BGI8
IDT71T75702S75PFI8	None	IDT71V2546SA100BQ	None
IDT71T75702S80BG	None	IDT71V2546SA100BQ8	None



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: SR-08-03R1

Discontinued Part#	Recommended Replacement Part#	Discontinued Part#	Recommended Replacement Part#
IDT71V2546SA100BQI	None	IDT71V2548S150PF8	None
IDT71V2546SA100BQI8	None	IDT71V2548S150PFI	None
IDT71V2546SA133BG	IDT71V2546S133BG	IDT71V2548S150PFI8	None
IDT71V2546SA133BG8	IDT71V2546S133BG8	IDT71V2548SA100BQ	None
IDT71V2546SA133BGI	IDT71V2546S133BGI	IDT71V2548SA100BQ8	None
IDT71V2546SA133BGI8	IDT71V2546S133BGI8	IDT71V2548SA100BQI	None
IDT71V2546SA133BQ	None	IDT71V2548SA100BQI8	None
IDT71V2546SA133BQ8	None	IDT71V2548SA133BQ	None
IDT71V2546SA133BQI	None	IDT71V2548SA133BQ8	None
IDT71V2546SA133BQI8	None	IDT71V2548SA133BQI	None
IDT71V2546SA150BG	IDT71V2546S150BG	IDT71V2548SA133BQI8	None
IDT71V2546SA150BG8	IDT71V2546S150BG8	IDT71V2548SA150BQ	None
IDT71V2546SA150BGI	None	IDT71V2548SA150BQ8	None
IDT71V2546SA150BGI8	None	IDT71V2548SA150BQI	None
IDT71V2546SA150BQ	None	IDT71V2548SA150BQI8	None
IDT71V2546SA150BQ8	None	IDT71V2548XS133BG	None
IDT71V2546SA150BQI	None	IDT71V2548XS133BG8	None
IDT71V2546SA150BQI8	None	IDT71V2556S100BG	IDT71V2556SA100BG
IDT71V2548S100BG	None	IDT71V2556S100BG8	IDT71V2556SA100BG8
IDT71V2548S100BG8	None	IDT71V2556S100BGI	IDT71V2556SA100BGI
IDT71V2548S100BGI	None	IDT71V2556S100BGI8	IDT71V2556SA100BGI8
IDT71V2548S100BGI8	None	IDT71V2556S100BQ	None
IDT71V2548S100PF	None	IDT71V2556S100BQ8	None
IDT71V2548S100PF8	None	IDT71V2556S100BQI	None
IDT71V2548S100PFG	None	IDT71V2556S100BQI8	None
IDT71V2548S100PFG8	None	IDT71V2556S133BG	IDT71V2556SA133BG
IDT71V2548S100PFI	None	IDT71V2556S133BG8	IDT71V2556SA133BG8
IDT71V2548S100PFI8	None	IDT71V2556S133BGI	IDT71V2556SA133BGI
IDT71V2548S133BG	None	IDT71V2556S133BGI8	IDT71V2556SA133BGI8
IDT71V2548S133BG8	None	IDT71V2556S133BQ	None
IDT71V2548S133BGI	None	IDT71V2556S133BQ8	None
IDT71V2548S133BGI8	None	IDT71V2556S133BQI	None
IDT71V2548S133BQ	None	IDT71V2556S133BQI8	None
IDT71V2548S133BQ8	None	IDT71V2556S150BQ	None
IDT71V2548S133PF	None	IDT71V2556S150BQ8	None
IDT71V2548S133PF8	None	IDT71V2556S166BG	IDT71V2556SA166BG
IDT71V2548S133PFI	None	IDT71V2556S166BG8	IDT71V2556SA166BG8
IDT71V2548S133PFI8	None	IDT71V2556S166BGI	None
IDT71V2548S150BG	None	IDT71V2556S166BGI8	None
IDT71V2548S150BG8	None	IDT71V2556S166BQ	None
IDT71V2548S150BGI	None	IDT71V2556S166BQ8	None
IDT71V2548S150BGI8	None	IDT71V2556SA100BQ	None
IDT71V2548S150PF	None	IDT71V2556SA100BQ8	None



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: SR-08-03R1

Discontinued Part#	Recommended Replacement Part#	Discontinued Part#	Recommended Replacement Part#
IDT71V2556SA100BQI	None	IDT71V2558S133PF8	None
IDT71V2556SA100BQI8	None	IDT71V2558S133PFI	None
IDT71V2556SA133BQ	None	IDT71V2558S133PFI8	None
IDT71V2556SA133BQ8	None	IDT71V2558S150PFG	None
IDT71V2556SA133BQG	None	IDT71V2558S150PFG8	None
IDT71V2556SA133BQG8	None	IDT71V2558S166BG	None
IDT71V2556SA133BQGI	None	IDT71V2558S166BG8	None
IDT71V2556SA133BQGI8	None	IDT71V2558S166BGI	None
IDT71V2556SA133BQI	None	IDT71V2558S166BGI8	None
IDT71V2556SA133BQI8	None	IDT71V2558S166PF	None
IDT71V2556SA150BQ	None	IDT71V2558S166PF8	None
IDT71V2556SA150BQ8	None	IDT71V2558S166PFG	None
IDT71V2556SA166BQ	None	IDT71V2558S166PFG8	None
IDT71V2556SA166BQ8	None	IDT71V2558S166PFI	None
IDT71V2556SA166BQG	None	IDT71V2558S166PFI8	None
IDT71V2556SA166BQG8	None	IDT71V2558S200BG	None
IDT71V2556SA166BQGI	None	IDT71V2558S200BG8	None
IDT71V2556SA166BQGI8	None	IDT71V2558S200PF	None
IDT71V2556SA166BQI	None	IDT71V2558S200PF8	None
IDT71V2556SA166BQI8	None	IDT71V2558SA100BG	None
IDT71V2558S100BG	None	IDT71V2558SA100BG8	None
IDT71V2558S100BG8	None	IDT71V2558SA133BG	None
IDT71V2558S100BGI	None	IDT71V2558SA133BG8	None
IDT71V2558S100BGI8	None	IDT71V2558XS133PF	None
IDT71V2558S100BQ	None	IDT71V2558XS133PF8	None
IDT71V2558S100BQ8	None	IDT71V2558XS200PF	None
IDT71V2558S100BQI	None	IDT71V2558XS200PF8	None
IDT71V2558S100BQI8	None	IDT71V2558XS200PFG	None
IDT71V2558S100PF	None	IDT71V2558XS200PFG8	None
IDT71V2558S100PF8	None	IDT71V2559S75BG	None
IDT71V2558S100PFG	None	IDT71V2559S75BG8	None
IDT71V2558S100PFG8	None	IDT71V2559S75BQ	None
IDT71V2558S100PFI	None	IDT71V2559S75BQ8	None
IDT71V2558S100PFI8	None	IDT71V2559S75PF	None
IDT71V2558S133BG	None	IDT71V2559S75PF8	None
IDT71V2558S133BG8	None	IDT71V2559S80BG	None
IDT71V2558S133BGI	None	IDT71V2559S80BG8	None
IDT71V2558S133BGI8	None	IDT71V2559S80BGI	None
IDT71V2558S133BQ	None	IDT71V2559S80BGI8	None
IDT71V2558S133BQ8	None	IDT71V2559S80BQ	None
IDT71V2558S133BQI	None	IDT71V2559S80BQ8	None
IDT71V2558S133BQI8	None	IDT71V2559S80PF	None
IDT71V2558S133PF	None	IDT71V2559S80PF8	None



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: SR-08-03R1

Discontinued Part#	Recommended Replacement Part#	Discontinued Part#	Recommended Replacement Part#
IDT71V2559S80PFI	None	IDT71V25761SA200BGI8	None
IDT71V2559S80PFI8	None	IDT71V25761SA200BQ	None
IDT71V2559S85BG	None	IDT71V25761SA200BQ8	None
IDT71V2559S85BG8	None	IDT71V25761SA200BQI	None
IDT71V2559S85BGI	None	IDT71V25761SA200BQI8	None
IDT71V2559S85BGI8	None	IDT71V25761YSA166BG	IDT71V25761S166BG
IDT71V2559S85BQ	None	IDT71V25761YSA166BG8	IDT71V25761S166BG8
IDT71V2559S85BQ8	None	IDT71V25761YSA166BGI	IDT71V25761S166BGI
IDT71V2559S85PF	None	IDT71V25761YSA166BGI8	IDT71V25761S166BGI8
IDT71V2559S85PF8	None	IDT71V25761YSA166BQ	None
IDT71V2559S85PFI	None	IDT71V25761YSA166BQ8	None
IDT71V2559S85PFI8	None	IDT71V25761YSA166BQGI	None
IDT71V2559SA75BG	None	IDT71V25761YSA166BQGI8	None
IDT71V2559SA75BG8	None	IDT71V25761YSA166BQI	None
IDT71V2559SA75BQ	None	IDT71V25761YSA166BQI8	None
IDT71V2559SA75BQ8	None	IDT71V25761YSA183BG	IDT71V25761S183BG
IDT71V2559SA80BG	None	IDT71V25761YSA183BG8	IDT71V25761S183BG8
IDT71V2559SA80BG8	None	IDT71V25761YSA183BGI	IDT71V25761S183BGI
IDT71V2559SA80BQ	None	IDT71V25761YSA183BGI8	IDT71V25761S183BGI8
IDT71V2559SA80BQ8	None	IDT71V25761YSA183BQ	None
IDT71V2559SA85BG	None	IDT71V25761YSA183BQ8	None
IDT71V2559SA85BG8	None	IDT71V25761YSA183BQI	None
IDT71V2559SA85BQ	None	IDT71V25761YSA183BQI8	None
IDT71V2559SA85BQ8	None	IDT71V25761YSA200BG	IDT71V25761S200BG
IDT71V25761SA166BG	IDT71V25761S166BG	IDT71V25761YSA200BG8	IDT71V25761S200BG8
IDT71V25761SA166BG8	IDT71V25761S166BG8	IDT71V25761YSA200BGI	None
IDT71V25761SA166BGI	IDT71V25761S166BGI	IDT71V25761YSA200BGI8	None
IDT71V25761SA166BGI8	IDT71V25761S166BGI8	IDT71V25761YSA200BQ	None
IDT71V25761SA166BQ	None	IDT71V25761YSA200BQ8	None
IDT71V25761SA166BQ8	None	IDT71V25761YSA200BQI	None
IDT71V25761SA166BQI	None	IDT71V25761YSA200BQI8	None
IDT71V25761SA166BQI8	None	IDT71V3556S100BG	IDT71V3556SA100BG
IDT71V25761SA183BG	IDT71V25761S183BG	IDT71V3556S100BG8	IDT71V3556SA100BG8
IDT71V25761SA183BG8	IDT71V25761S183BG8	IDT71V3556S100BGI	IDT71V3556SA100BGI
IDT71V25761SA183BGI	IDT71V25761S183BGI	IDT71V3556S100BGI8	IDT71V3556SA100BGI8
IDT71V25761SA183BGI8	IDT71V25761S183BGI8	IDT71V3556S100BQ	IDT71V3556SA100BQ
IDT71V25761SA183BQ	None	IDT71V3556S100BQ8	IDT71V3556SA100BQ8
IDT71V25761SA183BQ8	None	IDT71V3556S100BQG	IDT71V3556SA100BQG
IDT71V25761SA183BQI	None	IDT71V3556S100BQG8	IDT71V3556SA100BQG8
IDT71V25761SA183BQI8	None	IDT71V3556S100BQGI	IDT71V3556SA100BQGI
IDT71V25761SA200BG	IDT71V25761S200BG	IDT71V3556S100BQGI8	IDT71V3556SA100BQGI8
IDT71V25761SA200BG8	IDT71V25761S200BG8	IDT71V3556S100BQI	IDT71V3556SA100BQI
IDT71V25761SA200BGI	None	IDT71V3556S100BQI8	IDT71V3556SA100BQI8



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: SR-08-03R1

Discontinued Part#	Recommended Replacement Part#	Discontinued Part#	Recommended Replacement Part#
IDT71V3556S133BG	IDT71V3556SA133BG	IDT71V3557SA75BQG8	None
IDT71V3556S133BG8	IDT71V3556SA133BG8	IDT71V3557SA75BQGI	None
IDT71V3556S133BGI	IDT71V3556SA133BGI	IDT71V3557SA75BQGI8	None
IDT71V3556S133BGI8	IDT71V3556SA133BGI8	IDT71V3557SA75BQI	None
IDT71V3556S133BQ	IDT71V3556SA133BQ	IDT71V3557SA75BQI8	None
IDT71V3556S133BQ8	IDT71V3556SA133BQ8	IDT71V3557SA80BG	IDT71V3557S80BG
IDT71V3556S133BQG	IDT71V3556SA133BQG	IDT71V3557SA80BG8	IDT71V3557S80BG8
IDT71V3556S133BQG8	IDT71V3556SA133BQG8	IDT71V3557SA80BGI	IDT71V3557S80BGI
IDT71V3556S133BQGI	IDT71V3556SA133BQGI	IDT71V3557SA80BGI8	IDT71V3557S80BGI8
IDT71V3556S133BQGI8	IDT71V3556SA133BQGI8	IDT71V3557SA80BQ	None
IDT71V3556S133BQI	IDT71V3556SA133BQI	IDT71V3557SA80BQ8	None
IDT71V3556S133BQI8	IDT71V3556SA133BQI8	IDT71V3557SA80BQG	None
IDT71V3556S150BG	IDT71V3556SA150BG	IDT71V3557SA80BQG8	None
IDT71V3556S150BG8	IDT71V3556SA150BG8	IDT71V3557SA80BQGI	None
IDT71V3556S150BQ	IDT71V3556SA150BQ	IDT71V3557SA80BQGI8	None
IDT71V3556S150BQ8	IDT71V3556SA150BQ8	IDT71V3557SA80BQI	None
IDT71V3556S166BG	IDT71V3556SA166BG	IDT71V3557SA80BQI8	None
IDT71V3556S166BG8	IDT71V3556SA166BG8	IDT71V3557SA85BG	IDT71V3557S85BG
IDT71V3556S166BGI	IDT71V3556SA166BGI	IDT71V3557SA85BG8	IDT71V3557S85BG8
IDT71V3556S166BGI8	IDT71V3556SA166BGI8	IDT71V3557SA85BGI	IDT71V3557S85BGI
IDT71V3556S166BQ	IDT71V3556SA166BQ	IDT71V3557SA85BGI8	IDT71V3557S85BGI8
IDT71V3556S166BQ8	IDT71V3556SA166BQ8	IDT71V3557SA85BQ	None
IDT71V3556S166BQG	IDT71V3556SA166BQG	IDT71V3557SA85BQ8	None
IDT71V3556S166BQG8	IDT71V3556SA166BQG8	IDT71V3557SA85BQG	None
IDT71V3556S166BQGI	IDT71V3556SA166BQGI	IDT71V3557SA85BQG8	None
IDT71V3556S166BQGI8	IDT71V3556SA166BQGI8	IDT71V3557SA85BQGI	None
IDT71V3557S75BQ	None	IDT71V3557SA85BQGI8	None
IDT71V3557S75BQ8	None	IDT71V3557SA85BQI	None
IDT71V3557S80BQ	None	IDT71V3557SA85BQI8	None
IDT71V3557S80BQ8	None	IDT71V3558S100BG	None
IDT71V3557S80BQI	None	IDT71V3558S100BG8	None
IDT71V3557S80BQI8	None	IDT71V3558S100BQ	IDT71V3558SA100BQG
IDT71V3557S85BQ	None	IDT71V3558S100BQ8	IDT71V3558SA100BQG8
IDT71V3557S85BQ8	None	IDT71V3558S100BQI	IDT71V3558SA100BQGI
IDT71V3557S85BQI	None	IDT71V3558S100BQI8	IDT71V3558SA100BQGI8
IDT71V3557S85BQI8	None	IDT71V3558S133BG	None
IDT71V3557SA75BG	IDT71V3557S75BG	IDT71V3558S133BG8	None
IDT71V3557SA75BG8	IDT71V3557S75BG8	IDT71V3558S133BGI	None
IDT71V3557SA75BGI	IDT71V3557S75BGI	IDT71V3558S133BGI8	None
IDT71V3557SA75BGI8	IDT71V3557S75BGI8	IDT71V3558S133BQ	IDT71V3558SA133BQG
IDT71V3557SA75BQ	None	IDT71V3558S133BQ8	IDT71V3558SA133BQG8
IDT71V3557SA75BQ8	None	IDT71V3558S166BG	None
IDT71V3557SA75BQG	None	IDT71V3558S166BG8	None



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: SR-08-03R1

Discontinued Part#	Recommended Replacement Part#	Discontinued Part#	Recommended Replacement Part#
IDT71V3558S166BGI	None	IDT71V3559SA85BQI8	IDT71V3559S85BQI8
IDT71V3558S166BGI8	None	IDT71V35761S166BQ	IDT71V35761SA166BQG
IDT71V3558S200BG	None	IDT71V35761S166BQ8	IDT71V35761SA166BQG8
IDT71V3558S200BG8	None	IDT71V35761S166BQG	IDT71V35761SA166BQG
IDT71V3558S200BQ	IDT71V3558SA200BQG	IDT71V35761S166BQG8	IDT71V35761SA166BQG8
IDT71V3558S200BQ8	IDT71V3558SA200BQG8	IDT71V35761S166BQGI	IDT71V35761SA166BQGI
IDT71V3558S200BQI	IDT71V3558SA200BQGI	IDT71V35761S166BQGI8	IDT71V35761SA166BQGI8
IDT71V3558S200BQI8	IDT71V3558SA200BQGI8	IDT71V35761S166BQI	IDT71V35761SA166BQI
IDT71V3558SA100BG	None	IDT71V35761S166BQI8	IDT71V35761SA166BQI8
IDT71V3558SA100BG8	None	IDT71V35761S183BQ	IDT71V35761SA183BQG
IDT71V3558SA100BQ	IDT71V3558SA100BQG	IDT71V35761S183BQ8	IDT71V35761SA183BQG8
IDT71V3558SA100BQ8	IDT71V3558SA100BQG8	IDT71V35761S183BQG	IDT71V35761SA183BQG
IDT71V3558SA133BG	None	IDT71V35761S183BQG8	IDT71V35761SA183BQG8
IDT71V3558SA133BG8	None	IDT71V35761S183BQGI	None
IDT71V3558SA133BQ	IDT71V3558SA133BQG	IDT71V35761S183BQGI8	None
IDT71V3558SA133BQ8	IDT71V3558SA133BQG8	IDT71V35761S183BQI	None
IDT71V3559SA75BG	IDT71V3559S75BG	IDT71V35761S183BQI8	None
IDT71V3559SA75BG8	IDT71V3559S75BG8	IDT71V35761S200BQ	IDT71V35761SA200BQG
IDT71V3559SA75BQ	IDT71V3559S75BQ	IDT71V35761S200BQ8	IDT71V35761SA200BQG8
IDT71V3559SA75BQ8	IDT71V3559S75BQ8	IDT71V35761S200BQG	IDT71V35761SA200BQG
IDT71V3559SA75BQG	IDT71V3559S80BQG	IDT71V35761S200BQG8	IDT71V35761SA200BQG8
IDT71V3559SA75BQG8	IDT71V3559S80BQG8	IDT71V35761S200BQGI	IDT71V35761SA200BQGI
IDT71V3559SA75BQGI	None	IDT71V35761S200BQGI8	IDT71V35761SA200BQGI8
IDT71V3559SA75BQGI8	None	IDT71V35761S200BQI	IDT71V35761SA200BQI
IDT71V3559SA75BQI	IDT71V3559S75BQI	IDT71V35761S200BQI8	IDT71V35761SA200BQI8
IDT71V3559SA75BQI8	IDT71V3559S75BQI8	IDT71V35761SA166BQ	IDT71V35761SA166BQG
IDT71V3559SA80BG	IDT71V3559S80BG	IDT71V35761SA166BQ8	IDT71V35761SA166BQG8
IDT71V3559SA80BG8	IDT71V3559S80BG8	IDT71V35761SA166BQI	IDT71V35761SA166BQGI
IDT71V3559SA80BQ	IDT71V3559S80BQ	IDT71V35761SA166BQI8	IDT71V35761SA166BQGI8
IDT71V3559SA80BQ8	IDT71V3559S80BQ8	IDT71V35761SA183BQ	IDT71V35761SA183BQG
IDT71V3559SA80BQG	IDT71V3559S80BQG	IDT71V35761SA183BQ8	IDT71V35761SA183BQG8
IDT71V3559SA80BQG8	IDT71V3559S80BQG8	IDT71V35761SA183BQI	None
IDT71V3559SA80BQGI	None	IDT71V35761SA183BQI8	None
IDT71V3559SA80BQGI8	None	IDT71V35761SA200BQ	IDT71V35761SA200BQG
IDT71V3559SA85BG	IDT71V3559S85BG	IDT71V35761SA200BQ8	IDT71V35761SA200BQG8
IDT71V3559SA85BG8	IDT71V3559S85BG8	IDT71V35761SA200BQI	IDT71V35761SA200BQGI
IDT71V3559SA85BQ	IDT71V3559S85BQ	IDT71V35761SA200BQI8	IDT71V35761SA200BQGI8
IDT71V3559SA85BQ8	IDT71V3559S85BQ8	IDT71V35761YSA166BQ	IDT71V35761SA166BQG
IDT71V3559SA85BQG	IDT71V3559S85BQG	IDT71V35761YSA166BQ8	IDT71V35761SA166BQG8
IDT71V3559SA85BQG8	IDT71V3559S85BQG8	IDT71V35761YSA166BQI	IDT71V35761SA166BQGI
IDT71V3559SA85BQGI	None	IDT71V35761YSA166BQI8	IDT71V35761SA166BQGI8
IDT71V3559SA85BQGI8	None	IDT71V35761YSA183BQ	IDT71V35761SA183BQG
IDT71V3559SA85BQI	IDT71V3559S85BQI	IDT71V35761YSA183BQ8	IDT71V35761SA183BQG8



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: SR-08-03R1

Discontinued Part#	Recommended Replacement Part#	Discontinued Part#	Recommended Replacement Part#
IDT71V35761YSA183BQI	None	IDT71V65602S100BG8	None
IDT71V35761YSA183BQI8	None	IDT71V65602S100BQ	None
IDT71V35761YSA200BQ	IDT71V35761SA200BQG	IDT71V65602S100BQ8	None
IDT71V35761YSA200BQ8	IDT71V35761SA200BQG8	IDT71V65602S100PF	None
IDT71V35761YSA200BQI	IDT71V35761SA200BQGI	IDT71V65602S100PF8	None
IDT71V35761YSA200BQI8	IDT71V35761SA200BQGI8	IDT71V65602S100PFG	None
IDT71V3577SA75BG	None	IDT71V65602S100PFG8	None
IDT71V3577SA75BG8	None	IDT71V65602S100PFGI	None
IDT71V3577SA75BGG	None	IDT71V65602S100PFGI8	None
IDT71V3577SA75BGG8	None	IDT71V65602S133BG	None
IDT71V3577SA75BGGI	None	IDT71V65602S133BG8	None
IDT71V3577SA75BGGI8	None	IDT71V65602S133BQ	None
IDT71V3577SA75BQ	None	IDT71V65602S133BQ8	None
IDT71V3577SA75BQ8	None	IDT71V65602S133PF	None
IDT71V3577SA75BQG	None	IDT71V65602S133PF8	None
IDT71V3577SA75BQG8	None	IDT71V65602S133PFG	None
IDT71V3577SA75BQGI	None	IDT71V65602S133PFG8	None
IDT71V3577SA75BQGI8	None	IDT71V65602S133PFI	None
IDT71V3577SA75BQI	None	IDT71V65602S133PFI8	None
IDT71V3577SA75BQI8	None	IDT71V65602S150BG	None
IDT71V3577SA80BG	None	IDT71V65602S150BG8	None
IDT71V3577SA80BG8	None	IDT71V65602S150BQ	None
IDT71V3577SA80BGG	None	IDT71V65602S150BQ8	None
IDT71V3577SA80BGG8	None	IDT71V65602S150PF	None
IDT71V3577SA80BGGI	None	IDT71V65602S150PF8	None
IDT71V3577SA80BGGI8	None	IDT71V65602S150PFG	None
IDT71V3577SA80BQ	None	IDT71V65602S150PFG8	None
IDT71V3577SA80BQ8	None	IDT71V65602S150PFGI	None
IDT71V3577SA80BQG	None	IDT71V65602S150PFGI8	None
IDT71V3577SA80BQG8	None	IDT71V65602S150PFI	None
IDT71V3577SA80BQGI	None	IDT71V65602S150PFI8	None
IDT71V3577SA80BQGI8	None	IDT71V65602ZS133BG	None
IDT71V3577SA80BQI	None	IDT71V65602ZS133BG8	None
IDT71V3577SA80BQI8	None	IDT71V65802S100BG	None
IDT71V3577SA85BG	None	IDT71V65802S100BG8	None
IDT71V3577SA85BG8	None	IDT71V65802S100BQ	None
IDT71V3577SA85BGG	None	IDT71V65802S100BQ8	None
IDT71V3577SA85BGG8	None	IDT71V65802S100PF	None
IDT71V3577SA85BQ	None	IDT71V65802S100PF8	None
IDT71V3577SA85BQ8	None	IDT71V65802S100PFG	None
IDT71V3577SA85BQI	None	IDT71V65802S100PFG8	None
IDT71V3577SA85BQI8	None	IDT71V65802S133BG	None
IDT71V65602S100BG	None	IDT71V65802S133BG8	None



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: SR-08-03R1

Discontinued Part#	Recommended Replacement Part#	Discontinued Part#	Recommended Replacement Part#
IDT71V65802S133BQ	None	IDT71V67602S133BQI8	None
IDT71V65802S133BQ8	None	IDT71V67602S150BG	IDT71V67602S150BGG
IDT71V65802S133BQI	None	IDT71V67602S150BG8	IDT71V67602S150BGG8
IDT71V65802S133BQI8	None	IDT71V67602S150BGI	None
IDT71V65802S133PF	None	IDT71V67602S150BGI8	None
IDT71V65802S133PF8	None	IDT71V67602S150BQ	None
IDT71V65802S133PFG	None	IDT71V67602S150BQ8	None
IDT71V65802S133PFG8	None	IDT71V67602S150BQI	None
IDT71V65802S150BG	None	IDT71V67602S150BQI8	None
IDT71V65802S150BG8	None	IDT71V67602S166BG	IDT71V67602S166BGG
IDT71V65802S150BGG	None	IDT71V67602S166BG8	IDT71V67602S166BGG8
IDT71V65802S150BGG8	None	IDT71V67602S166BQ	None
IDT71V65802S150BQ	None	IDT71V67602S166BQ8	None
IDT71V65802S150BQ8	None	IDT71V67602S166BQG	None
IDT71V65802S150PF	None	IDT71V67602S166BQG8	None
IDT71V65802S150PF8	None	IDT71V67602S166BQGI	None
IDT71V65802ZS133BG	None	IDT71V67602S166BQGI8	None
IDT71V65802ZS133BG8	None	IDT71V67602S166BQI	None
IDT71V67602S133BG	IDT71V67602S133BGG	IDT71V67602S166BQI8	None
IDT71V67602S133BG8	IDT71V67602S133BGG8	IDT71V67802S133PF	None
IDT71V67602S133BGI	None	IDT71V67802S133PF8	None
IDT71V67602S133BGI8	None	IDT71V67802S133PFI	None
IDT71V67602S133BQ	None	IDT71V67802S133PFI8	None
IDT71V67602S133BQ8	None	IDT71V67802S150PF	None
IDT71V67602S133BQG	None	IDT71V67802S150PF8	None
IDT71V67602S133BQG8	None	IDT71V67802S150PFI	None
IDT71V67602S133BQGI	None	IDT71V67802S150PFI8	None
IDT71V67602S133BQGI8	None	IDT71V67802S166PF	None
IDT71V67602S133BQI	None	IDT71V67802S166PFI8	None



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA 95138
Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: SR-08-03R1

Discontinued Part#	Recommended Replacement Part#	Discontinued Part#	Recommended Replacement Part#
IDT71V3557SA75BGG	IDT71V3557S75BGG	IDT71V3557SA80BGGI	None
IDT71V3557SA75BGG8	IDT71V3557S75BGG8	IDT71V3557SA80BGGI8	None
IDT71V3557SA75BGGI	None	IDT71V3557SA85BGG	IDT71V3557S75BGG
IDT71V3557SA75BGGI8	None	IDT71V3557SA85BGG8	IDT71V3557S75BGG8
IDT71V3557SA80BGG	IDT71V3557S75BGG	IDT71V3557SA85BGGI	None
IDT71V3557SA80BGG8	IDT71V3557S75BGG8	IDT71V3557SA85BGGI8	None