

# **PRODUCT ADVISORY**

## **Data Sheet Specification Change for Intersil QLx4270\* Product**

**Refer to:  
PA10022**

**Date: March 5, 2010**

March 5, 2010

To: Our Valued Intersil Customers

**Subject: Data Sheet Specification Change for Intersil QLx4270\* Product**

This advisory is to inform you that Intersil has updated the data sheet specification for the listed QLx4270\* products. The updates consist of the following:

- i) The pin name and description for Pin 24 was changed from "NC" to "GND" in the Pin Configuration layout on sheet 2 and Pin Descriptions table on sheet 3.
- ii) The pin name and description for Pin 38 was changed from "NC" to "BGREF" in the Pin Configuration layout on sheet 2 and Pin Descriptions table on sheet 3.

The updated data sheet, FN6972 dated March 3, 2010, is included as a separate attachment with the changes shaded in yellow.

Products affected: **QLx4270RIQSR QLx4270RIQT7**

Intersil will take all necessary actions to conform to customer requirements and to ensure the continued high quality and reliability of Intersil products being supplied. Customers may expect to continue receiving product processed to the same established conditions and systems used for screening of material supplied today.

If you have concerns with this change notice, Intersil must hear from you immediately. Please contact the nearest Intersil Sales Office or call the Intersil Corporate line at 1-888-468-3774, in the United States, or 1-321-724-7143 outside of the United States.

*Jon Brewster*

Jon Brewster  
Intersil Corporation

PA10022

CC: J. Touvell E. Lee J. Mitchell M. Casino