

# RENESAS TECHNICAL UPDATE

TOYOSU FORESIA, 3-2-24, Toyosu, Koto-ku, Tokyo 135-0061, Japan  
Renesas Electronics Corporation

Product Category	MPU/MCU		Document No.	TN-SY*-A0051A/E	Rev.	1.00
Title	Errata for User's Manual regarding the overview		Information Category	Technical Notification		
Applicable Product	Renesas Synergy™ S1JA MCU Group	Lot No.	Reference Document	S1JA Microcontroller Group User's Manual Rev.1.40		
		All				

The specified Renesas Synergy S1JA User's Manual has incorrect statements about the overview.

Page 51 of 1285

Table 1.7 Communication interface (2 of 2)

USB 2.0 Full-Speed (USB-FS) module

#### Incorrect

The USB 2.0 Full-Speed (USBFS) module can operate as a **host controller or** device controller.

#### Correct

The USB 2.0 Full-Speed (USBFS) module can operate as a device controller.