

## Corrections to "HI7000/4 Series User's Manual Rev.6.00"

We notify corrections to "HI7000/4 Series User's Manual Rev.6.00" Document No. REJ10B0060-0600.

### 1. Corrections

#### 1.1 Page 409, body of Table C.2; first row from the top (Item "Task exception processing routine") in the HI7000/4, HI7700/4, and HI7750/4 columns

Read	For
HI7000/4: 144	HI7000/4: 172
HI7700/4: 144 *2	HI7700/4: 172 *2
HI7750/4: 152	HI7750/4: 180

#### 1.2 Page 410, body of table C.3; last row from the top (Function "texrtn") in the Size(Byte) column

Read "144 + 16 = 160" for "172 + 16 = 188"

#### 1.3 Page 413, body of Table C.6; second row from the top (Item "Calls service call") in the HI7000/4 Direct Interrupt Handler, HI7000/4 Normal Interrupt Handler, HI7700/4, HI7750/4 columns

Read	For
HI7000/4 Direct Interrupt Handler: 140 Normal Interrupt Handler: 140	HI7000/4 Direct Interrupt Handler: 168 Normal Interrupt Handler: 168

HI7700/4: 140 \*3

HI7700/4: 168 \*3

HI7750/4: 144

HI7750/4: 172

## 2. "HI7000/4 Series Supplementary Information" revised

The above errata have been added to the following document:

Title: HI7000/4 Series Supplementary Information

Revision: Rev.1.02

Document No.: R20UT0478EJ0102

The above document will be published on the Web page on April 5 at [HERE](#).

---

### [\[Disclaimer\]](#)

[The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.](#)

[© 2010-2016 Renesas Electronics Corporation. All rights reserved.](#)