RENESAS Tool News

RENESAS TOOL NEWS on April 16, 2011: 110416/tn4

Corrections to the Notes on Connecting MCUs of the R32C/100 Series --Additional Documents for the E8a Emulator User's Manual

We inform you about corrections to the notes on connecting MCUs of the R32C/100 series-additional documents for the E8a emulator user's manual.

1. Documents Concerned

E8a Emulator Additional Document for User's Manual Notes on Connecting MCUs of the R32C/100 series Document Nos.:

> REJ10J1877-0100 (Rev.1.00) REJ10J1877-0200 (Rev.2.00) REJ10J1877-0201 (Rev.2.01) REJ10J1877-0300 (Rev.3.00) REJ10J1877-0400 (Rev.4.00) REJ10J1877-0500 (Rev.5.00) REJ10J1877-0600 (Rev.6.00)

2. Corrections

2.1 In All the Documents Listed Above

- (1) Page 21, Section 4.3.1, 2nd item of the bulleted listDelete this item. (Memory expansion mode: See Figure 4.18.)
- (2) Page 22

Delete the whole of Figure 4.18 and all the Notes.

(3) Page 24, under the heading of Section 2 Delete the whole of Figure 4.21 and all the Note.

2.2 In Document Nos. REJ10J1877-0100 (Rev.1.00) through REJ10J1877-0300 (Rev.3.00)

(1) Page 37, Table 6.5, lowest three addresses in Address column

Read	For
FFFFFECh	FFFFFFCh
FFFFFFEDh	FFFFFFDh
FFFFFFEEh	FFFFFFEh

2.3 In Document Nos. RJJ10J2232-0400 (Rev.4.00) and RJJ10J2232-0500 (Rev.5.00)

(1) Page 37, Table 6.6, lowest three addresses in Address column

Read	For
FFFFFECh	FFFFFFCh
FFFFFEDh	FFFFFFDh
FFFFFFEEh	FFFFFFEh

2.4 In Document No. RJJ10J2232-0600 (Rev.6.00)

(1) Page 38, Table 6.6, lowest three addresses in Address column

Read	For
FFFFFECh	FFFFFFCh
FFFFFEDh	FFFFFFDh
FFFFFFEEh	FFFFFFEh

To see these corrections, go to:

http://tool-support.renesas.com/eng/toolnews/110416/tn4.htm This Web page will be opened from May 11.

Also you can see the corrected document concerned, Document No. R20UT0607EJ0700 (Rev.7.00), at: http://www.renesas.com/e8a_document

The above URL is one of our global sites.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.