

RENESAS TOOL NEWS on January 17, 2012: 120117/tn1

A Patch Supplied for High-performance Embedded Workshop

We start supplying a patch for eliminating the following problem: which was notified in RENESAS TOOL NEWS Document No. 111213/tn1.

· With selecting build options

1. Products Involved

High-performance Embedded Workshop V.4.09.00 or later which are used with C/C++ compiler package for SuperH family V.9.04 Release 01

2. Description

We supply a patch for eliminating the following problem, which was notified in RENESAS TOOL NEWS Document No. 111213/tn1.

- With selecting build options

For details see at:

https://www.renesas.com/search/keyword-search.html#genre=document&q=111213tn1

3. How to Obtain the Patch

Download the HEW_PATCH_120117.zip file (647 KB) from HERE.

4. How to Apply the Patch

To apply the patch, exit High-performance Embedded Workshop if it is operating and then follow these steps:

- (1) Decompress the downloaded HEW PATCH 120117.zip file in any directory.
- (2) Execute the decompressed PatchTool.exe file.

- (3) In the list of the compilers to be updated, select the check box for the compiler to which you want to apply the patch; then click the Update button.
- (4) The following message appears in the dialog box: "Close all High-performance Embedded Workshop.

Click OK to start the update."

So exit High-performance Embedded Workshop if operating; then click OK.

- (5) When update is completed, and the message "The update has finished" displayed, click OK.
- (6) If you have installed two or more High-performance Embedded Workshop programs in the PC under multi-installation control, switch the active one to another by using Install Manager, and repeat the steps (2) through (5).

5. How to Check the Version of the Updated DLL Files

When the patch is applied, DLL files concerned are updated.

To check to see the version of the updated DLL files, follow these steps:

- (1) Start Windows Explorer.
- (2) Find the following DLL files that corresponds to your High-performance Embedded Workshop in the subdirectory where you have installed
 - Shbp.dll

Resides under \text{\text{YTools}\text{\text{Renesas}\text{\text{SH}\text{\text{\text{\text{Y}}}}_4_1\text{\text{\text{hew}}}

- ResShbp.dll

Resides under \text{\text{YTools}\text{\text{Renesas}\text{\text{SH}\text{\text{\text{\text{Y}}}}}\delta_1\text{\text{\text{hew}}}

- (3) Right-click the DLL file concerned to open a pop-up menu; then select Properties. The properties of the file are displayed.
- (4) Click the Version tab and check to see that the version number of the file is the following respectively:
 - 6.9.1.1 in Shbp.dll
 - 6.9.1.1 in ResShbp.dll

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.