

RENESAS TOOL NEWS on June 16, 2015: 150616/tn8

## Revision of the AP4 Coding Assistance Tool for RZ

We are revising the AP4 for RZ from V1.00.00 to V1.01.00.

---

### 1. Description of Revision

#### (a) Addition of supported compilers

- We have added support for the Development Studio (DS-5(TM)) from ARM(R) Limited as a software development tool.

Contact ARM Limited with inquiries regarding or orders for the Development Studio (DS-5).

ARM Limited Web site:<http://www.arm.com/contact-us/>

Note: ARM and DS-5 are registered trademarks or trademarks of ARM Limited.

#### (b) The following point announced in a cautionary note (issue No. 150516/tn2 of Renesas Tool News) will be fixed.

The problem regarding the point below will be fixed.

- I2C Bus Interface (RIICa)

Applicable products: RZ/T1 group

For details of the problem, refer to the URL below.

<https://www.renesas.com/search/keyword-search.html#genre=document&q=150516tn2>

### 2. Obtaining the Product

Download the installer from the URL below to install the program.

The program will be available from June 22.

[https://www.renesas.com/applilet\\_download](https://www.renesas.com/applilet_download)

---

#### [Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

