# RENESAS TOOL NEWS

# [Notes]

# C Compiler CA78K0R for RL78 Family and 78K0R

R20TS0064EJ0100 Rev.1.00 Jul. 16, 2016

# C Compiler CC78K0R for 78K0R

## C Compiler CA78K0 and CC78K0 for 78K0

#### Outline

When using the CA78K0R C Compiler for the RL78 family and 78K0R, the CC78K0R C Compiler for the 78K0R, and the CA78K0/CC78K0 C Compiler for the 78K0, take note of the problems described in this note regarding the following points.

1. Notes when writing #pragma section statement in the nested header file

#### 1. Notes when writing #pragma section statement in the nested header file

### 1.1 Applicable Products

- > CA78K0R V1.70 to V1.72 (CS+ Integrated Development Environment)
- > CA78K0R V1.20 to V1.70 (CubeSuite+ Integrated Development Environment)
- CA78K0R V1.00 to V1.10 (CubeSuite Integrated Development Environment)
- CC78K0R V1.00 to V2.13 (PM+ Integrated Development Environment)
- CA78K0 V1.30 (CS+ Integrated Development Environment)
- CA78K0 V1.20 to V1.21 (CubeSuite+ Integrated Development Environment)
- CA78K0 V1.00 to V1.11 (CubeSuite Integrated Development Environment)
- CC78K0 V1.00 to V4.10 (PM+ Integrated Development Environment)

### 1.2 Details

When #pragma section statement is used in the nested header file, data may not be placed in the specified section.

### 1.3 Conditions

This problem may arise when all the conditions below are met:

- (1) C source file includes a header file (hereinafter "file A"), and the file A includes the other header file (hereinafter "file B").
- (2) #pragma section statement is used in the file A or B (\*1), except the case when it is used in the C source file.

\*1: This applies to the header file that the file B further includes as well.



Example

### 1.4 Workaround

Do not write #pragma section statement in the file A and B.

Note: This applies to the header file that the file B further includes as well.

### 1.5 Schedule for Fixing the Problem

There is no plan to resolve this issue.



### **Revision History**

		Description	
Rev.	Date	Page	Summary
1.00	Jul. 16, 2016	-	First edition issued

TOYOSU FORESIA, 3-2-24 Toyosu, Koto-ku, Tokyo 135-0061 Japan Renesas Electronics Corporation

Inquiry
http://www.renesas.com/contact/

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication.

Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

All trademarks and registered trademarks are the property of their respective owners.

