Old Company Name in Catalogs and Other Documents

On April 1st, 2010, NEC Electronics Corporation merged with Renesas Technology Corporation, and Renesas Electronics Corporation took over all the business of both companies. Therefore, although the old company name remains in this document, it is a valid Renesas Electronics document. We appreciate your understanding.

Renesas Electronics website: http://www.renesas.com

April 1st, 2010 Renesas Electronics Corporation

Issued by: Renesas Electronics Corporation (http://www.renesas.com)

Send any inquiries to http://www.renesas.com/inquiry.

http://www.renesas.com/fmwk.jsp?cnt=/download_search_results.jsp&fp=/support/downloads/download_results&layerId=1161, http://www.renesas.com/fmwk.jsp?cnt=/download_search_results.jsp&fp=/support/downloads/download_results&layerId=1162, http://www.renesas.com/fmwk.jsp?cnt=/download_search_results.jsp&fp=/support/downloads/download_results&layerId=1163

date: 2002/09/24

HITACHI SEMICONDUCTOR TECHNICAL UPDATE

Classification of Production	Development environment			No	TN-EML-096A/E	Rev.	1	
THEME	Problem on Using the PCMCIA and PCI Drivers for Windows [®] 2000 with the E10A/E10T/E6000/E8000 Emulator		Classification of Information	 Spec change Supplement of Documents Limitation of Use 		5. Change	 Change of Mask Change of Production Line 	
PRODUCT NAME	E10A/E10T/E6000/E8000 Emulator	Lot No. PCMCIA and PCI drivers for Windows © 2000 dated May/2002 or before	Reference Documents		None	Effective	Date	

The E10A/E10T/E6000/E8000 emulator may not be started up correctly when the emulator is connected to certain host computer, for which Windows[®] 2000 or Windows[®] XP has been installed, via the PCMCIA or PCI interface.

[Countermeasure]

(1) Select the emulator you use and download the driver software for correction from the following URL address: <u>http://www.hitachisemiconductor.com/sic/jsp/japan/eng/products/mpumcu/tool/download_index.html</u>

(2) Expand the file that you have downloaded. Then follow the installation procedure that is attached.

Note: Windows[®] is a registered trademark of Microsoft Corporation in the United States.