



Integrated Device Technology, Inc.  
 2975 Stender Way, Santa Clara, CA - 95054  
 Phone #: (408) 727-6116 Fax #: (408) 727-2328

## PRODUCT DISCONTINUANCE NOTICE (PDN)

PDN #:	LOGIC-00-14	Last Buy Date:	10/20/2001
Issue Date:	10/20/2000	Last Ship Date:	1/20/2002
		(3 months after last buy date)	

**PRODUCT(S) AFFECTED:** **ATTACHMENT**  Yes  No  
*(List Replacement Part #(s), if any)*

Obsolete selected military FCT parts (Standard IDT part # and DESC versions). Please see attachment for details.  
 No replacement part # are available for the obsoleted devices.

**REASON FOR DISCONTINUANCE:**

- Replace slower speed with faster speed offerings  Other:
- Obsolete Fab Technology / Process
- Obsolete Assembly Technology / Process
- Obsolete Package / Material
- Declined Market

**CUSTOMER NOTIFICATION:**

As a result of discontinuance reason(s) listed above, IDT has decided to discontinue certain products and notify you through this Product Discontinuance Notice (PDN). We recommend you to check detailed specifications before converting to equivalent devices offered. Please use acknowledgement below or E-Mail to request additional information.

*If you have any questions, please feel free to contact your local IDT distributor or sales representative.*

Customer: _____	E-Mail Address: _____
Name/Date: _____	Phone#: _____
Title: _____	Fax#: _____

**CUSTOMER COMMENTS:** \_\_\_\_\_

**IDT ACKNOWLEDGEMENT:**

Received By: \_\_\_\_\_ Date: \_\_\_\_\_



Integrated Device Technology, Inc.  
2975 Stender Way, Santa Clara, CA - 95054  
Phone #: (408) 727-6116

Attachment  
PDN # LOGIC-00-14

<b>IDT Part #</b>	<b>DESC Part #</b>	<b>Comments</b>
54FCT162240TEB	5962-9227001MXA	No Replacement Part #
54FCT162240ATEB	5962-9227002MXA	No Replacement Part #
54FCT162240CTEB	5962-9227003MXA	No Replacement Part #
54FCT162260ATEB		No Replacement Part #
54FCT162260CTEB		No Replacement Part #
54FCT162344ATEB		No Replacement Part #
54FCT162344CTEB		No Replacement Part #
54FCT162500ATEB		No Replacement Part #
54FCT162500CTEB		No Replacement Part #
54FCT162501ATEB	5962-9227601MXA	No Replacement Part #
54FCT162501CTEB	5962-9227602MXA	No Replacement Part #
54FCT16260ATEB		No Replacement Part #
54FCT16260CTEB		No Replacement Part #
54FCT162646TEB	5962-9227801MXA	No Replacement Part #
54FCT162646ATEB	5962-9227802MXA	No Replacement Part #
54FCT162646CTEB	5962-9227803MXA	No Replacement Part #
54FCT162701TEB		No Replacement Part #
54FCT162701ATEB		No Replacement Part #
54FCT162827ATEB	5962-9228101MXA	No Replacement Part #
54FCT162827BTEB	5962-9228102MXA	No Replacement Part #
54FCT162827CTEB	5962-9228103MXA	No Replacement Part #
54FCT162952ATEB	5962-9228301MXA	No Replacement Part #
54FCT162952BTEB	5962-9228302MXA	No Replacement Part #
54FCT162952CTEB	5962-9228303MXA	No Replacement Part #
54FCT16500ATEB		No Replacement Part #
54FCT16500CTEB		No Replacement Part #
54FCT16501ATEB		No Replacement Part #
54FCT16501CTEB		No Replacement Part #
54FCT16652TEB		No Replacement Part #
54FCT16652ATEB		No Replacement Part #
54FCT16652CTEB		No Replacement Part #
54FCT2244TDB	5962-9301901MRA	No Replacement Part #
54FCT2244TEB	5962-9301901MSA	No Replacement Part #
54FCT2244TLB	5962-9301901M2A	No Replacement Part #
54FCT2244ATDB	5962-9301902MRA	No Replacement Part #
54FCT2244ATEB	5962-9301902MSA	No Replacement Part #
54FCT2244ATLB	5962-9301902M2A	No Replacement Part #
54FCT2244CTDB	5962-9301903MRA	No Replacement Part #
54FCT2244CTEB	5962-9301903MSA	No Replacement Part #
54FCT2244CTLB	5962-9301903M2A	No Replacement Part #
54FCT2245TDB	5962-9302001MRA	No Replacement Part #
54FCT2245TEB	5962-9302001MSA	No Replacement Part #
54FCT2245TLB	5962-9302001M2A	No Replacement Part #
54FCT2245ATDB	5962-9302002MRA	No Replacement Part #



Integrated Device Technology, Inc.  
2975 Stender Way, Santa Clara, CA - 95054  
Phone #: (408) 727-6116

<b>IDT Part #</b>	<b>DESC Part #</b>	<b>Comments</b>
54FCT2245ATEB	5962-9302002MSA	No Replacement Part #
54FCT2245ATLB	5962-9302002M2A	No Replacement Part #
54FCT2245CTDB	5962-9302003MRA	No Replacement Part #
54FCT2245CTEB	5962-9302003MSA	No Replacement Part #
54FCT2245CTLB	5962-9302003M2A	No Replacement Part #
54FCT2373TDB	5962-9302501MRA	No Replacement Part #
54FCT2373TEB	5962-9302501MSA	No Replacement Part #
54FCT2373TLB	5962-9302501M2A	No Replacement Part #
54FCT2373ATDB	5962-9302502MRA	No Replacement Part #
54FCT2373ATEB	5962-9302502MSA	No Replacement Part #
54FCT2373ATLB	5962-9302502M2A	No Replacement Part #
54FCT2373CTDB	5962-9302503MRA	No Replacement Part #
54FCT2373CTEB	5962-9302503MSA	No Replacement Part #
54FCT2373CTLB	5962-9302503M2A	No Replacement Part #
54FCT2374TDB	5962-9302601MRA	No Replacement Part #
54FCT2374TEB	5962-9302601MSA	No Replacement Part #
54FCT2374TLB	5962-9302601M2A	No Replacement Part #
54FCT2374ATDB	5962-9302602MRA	No Replacement Part #
54FCT2374ATEB	5962-9302602MSA	No Replacement Part #
54FCT2374ATLB	5962-9302602M2A	No Replacement Part #
54FCT2374CTDB	5962-9302603MRA	No Replacement Part #
54FCT2374CTEB	5962-9302603MSA	No Replacement Part #
54FCT2374CTLB	5962-9302603M2A	No Replacement Part #