



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA 95138
Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

PDN #: U-10-20R1

Last Buy Deadline for Submission of Order: 1-Jun-2011

Issue Date: 17-Jan-2011

Last Eligible Ship Date: 1-Sep-2011

Contact: Russell Willner
Title: Marketing Manager - Micro Clock Products
Phone #: 408-284-6564
Fax #: 408-284-2774
E-mail: Russell.Willner@idt.com

PRODUCT(S) AFFECTED:

ATTACHMENT

☒ Yes ☐ No

(List Replacement Part #(s), if any)

Revision 1: This revised notice is to remove 6 part#s namely 9263AGLF, 9263AGLFT, 422CK-07LF, 422CK-07LFT, 1493EG-18LF and 1493EG-18LFT from the product discontinuance notice. Last buy and last ship dates remain unchanged. Refer to Attachment I for the updated product discontinuance list.

REASON FOR DISCONTINUANCE:

☐ Replace slower speed with faster speed offerings

☐ Other:

☐ Obsolete Fab Technology / Process

☐ Obsolete Assembly Technology / Process

☐ Obsolete Package / Material

☒ Declined Market

CUSTOMER NOTIFICATION:

As a result of discontinuance reason(s) listed above, IDT has decided to discontinue certain products and notify you through this Product Discontinuance Notice (PDN). We recommend you to check detailed specifications before converting to equivalent devices offered. Please use acknowledgement below or E-Mail to request additional information.

Last time buy orders may be submitted any time prior to the date indicated above. All orders shall be subject to acceptance by IDT at its sole discretion unless otherwise agreed by IDT in writing.

If you have any questions, please feel free to contact your local IDT distributor or sales representative.

Customer: _____

E-Mail Address: _____

Name/Date: _____

Phone#: _____

Title: _____

Fax# : _____

CUSTOMER COMMENTS:

IDT ACKNOWLEDGEMENT:

Received By: _____

Date: _____



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA 95138
Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: U-10-20R1

Affected Part Number

Discontinued Part#	Replacement Part#
1493BG-18LF	None
1493BG-18LFT	None
1493DG-18LF	None
1493DG-18LFT	None
1493G-18LF	None
1493G-18LFT	None
422AG-07LF	None
422AG-07LFT	None
422BG-07LF	None
422BG-07LFT	None
626BGLF	None
626BGLFT	None
9218AGLF	None
9218AGLFT	None
9218BGLF	None
9218BGLFT	None
9249AGLF	None
9249AGLFT	None