



Integrated Device Technology, Inc.
2975 Stender Way, Santa Clara, CA - 95054
Phone #: (408) 727-6116 Fax #: (408) 727-2328

PRODUCT DISCONTINUANCE NOTICE (PDN)

PDN #: **F-03-01** Last Buy Date: May 31, 2004
Issue Date: May 15, 2003 Last Ship Date: August 31, 2004
(3 months after last buy date)

PRODUCT(S) AFFECTED: **ATTACHMENT** Yes No
(List Replacement Part #(s), if any)

In order to increase manufacturing efficiency, the 48 pin TSSOP package option for the IDT72V898x family has been discontinued.

Device	Package	Replacment	
		Pin-to-pin	Other Package Options Available
IDT72V8980PA	48-TSSOP	N/A	44-PQFP (DB), 44-PLCC(J), 48-SSOP (PV)
IDT72V8981PA	48-TSSOP	N/A	44-PQFP (DB), 44-PLCC(J)
IDT72V8985PA	48-TSSOP	N/A	44-PQFP (DB), 44-PLCC(J), 48-SSOP (PV)
IDT72V8988PA	48-TSSOP	N/A	44-PQFP (DB), 44-PLCC(J)

REASON FOR DISCONTINUANCE:

- Replace slower speed with faster speed offerings
 - Obsolete Fab Technology / Process
 - Obsolete Assembly Technology / Process
 - Obsolete Package / Material
 - Declined Market
- Other: _____

CUSTOMER NOTIFICATION:

As a result of discontinuance reason(s) listed above, IDT has decided to discontinue certain products and notify you through this Product Discontinuance Notice (PDN). We recommend you to check detailed specifications before converting to equivalent devices offered. Please use acknowledgement below or E-Mail to request additional information.

If you have any questions, please feel free to contact your local IDT distributor or sales representative.

Customer: _____ E-Mail Address: _____
Name/Date: _____ Phone#: _____
Title: _____ Fax# : _____

CUSTOMER COMMENTS: _____

IDT ACKNOWLEDGEMENT:

Received By: _____ Date: _____