

Integrated Device Technology, Inc. 2975 Stender Way, Santa Clara, CA - 95054

Phone #: (408) 727-6116 Fax #: (408) 727-2328

PRODUCT DISCONTINUANCE NOTICE (PDN)

PDN #:	I-01-03		Last Buy Date:	October 29, 200	2
Issue Date:	October 29, 2001		Last Ship Date:	January 29, 2003	3
			(3 months after last	buy date)	
PRODUCT(S) . (List Replacement			ATTACHMENT	☐ Yes	■ No
IDT79RV30	81-25DL	IDT79RC64V474-250D	Z IDT79R	V5000-180G	
IDT79RV3081-25PF		IDT79RC64V474-250DZI IDT79RV5000-200G			
IDT79RV30	81-33DL	IDT79RC64V475-250D	P		
IDT79RV30	81-33PF	IDT79RC64V475-250D	PI		
IDT79RV30	81-40DL				
Note: There are no replacement part #s available REASON FOR DISCONTINUANCE:					
 □ Replace slower speed with faster speed offerings □ Obsolete Fab Technology / Process 					
	,	/ Flocess			
	kage / Material				
■ Declined Man	rket				
As a result of di through this Pro converting to eq	oduct Discontinuand quivalent devices of	n(s) listed above, IDT has be Notice (PDN). We reconferred. Please use acknowledge.	mmend you to check of ledgement below or E	detailed specification -Mail to request ad	ons before ditional information.
If you have any questions, please feel free to contact your local IDT distributor or sales representative.					
Customer:			E-Mail Address:		
Name/Date:			Phone#:		
Title:			Fax#:		
CUSTOMER C	COMMENTS:				
IDT ACKNOV	VLEDGEMENT:				
Received By:			Date:		