



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA - 95138

PRODUCT/PROCESS CHANGE NOTICE (PCN)

PCN #: A0705-03 DATE: 20-Sep-2007 Product Affected: SOIC and PLCC (Green Package) Refer to Attachment II for the affected part numbers Date Effective: 20-Dec-2007	MEANS OF DISTINGUISHING CHANGED DEVICES: <input type="checkbox"/> Product Mark <input checked="" type="checkbox"/> Back Mark Lot # will have a "V" prefix <input type="checkbox"/> Date Code <input type="checkbox"/> Other
---	---

Contact: Geoffrey Cortes Title: Product Quality Assurance Phone #: (408) 284-8321 Fax #: (408) 284-1450 E-mail: Geoffrey.Cortes@idt.com	Attachment: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No Samples: Please contact your local sales representative for sample request & availability.
---	--

DESCRIPTION AND PURPOSE OF CHANGE:

<input type="checkbox"/> Die Technology <input type="checkbox"/> Wafer Fabrication Process <input type="checkbox"/> Assembly Process <input type="checkbox"/> Equipment <input type="checkbox"/> Material <input type="checkbox"/> Testing <input checked="" type="checkbox"/> Manufacturing Site <input type="checkbox"/> Data Sheet <input type="checkbox"/> Other	<p>This notification is to advise our customers that IDT is adding MMT, Thailand as an alternate assembly facility for SOIC and PLCC green packages. There is no change to the moisture performance of these packages.</p> <p>Attachment I details the qualification data for this change and Attachment II shows the affected list of part numbers.</p>
--	--

RELIABILITY/QUALIFICATION SUMMARY:

Refer to qualification data shown in attachment I.

CUSTOMER ACKNOWLEDGMENT OF RECEIPT:

IDT records indicate that you require written notification of this change. Please use the acknowledgement below or E-Mail to grant approval or request additional information. If IDT does not receive acknowledgement within 30 days of this notice it will be assumed that this change is acceptable.

IDT reserves the right to ship either version manufactured after the process change effective date until the inventory on the earlier version has been depleted.

Customer: _____	<input type="checkbox"/> <i>Approval for shipments prior to effective date.</i>
Name/Date: _____	E-Mail Address: _____
Title: _____	Phone# /Fax# : _____

CUSTOMER COMMENTS: _____

IDT ACKNOWLEDGMENT OF RECEIPT:

RECD. BY: _____ DATE: _____



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA - 95138

PRODUCT/PROCESS CHANGE NOTICE (PCN)

ATTACHMENT I - PCN # : A0705-03

PCN Type: Manufacturing Site - Alternate Assembly Location

Data Sheet Change: None

No change in moisture sensitivity level (MSL)

Detail Of Change:

This notification is to advise our customers that IDT is adding MMT, Thailand as an alternate assembly facility for SOIC and PLCC green packages. There is no change to the moisture performance of these packages using the assembly material set as listed in the tables under each group.

There is no change in the moisture sensitivity level (MSL).

Attachment II shows the affected part numbers.

Sample Availability:

Samples for each package type are available for customer evaluation, but may not be available for all devices.

Please contact your local IDT sales representative for your sample request and availability.



PRODUCT/PROCESS CHANGE NOTICE (PCN)

ATTACHMENT I - PCN # : A0705-03

Qualification Information and Qualification Data:

GROUP 1:

Affected Packages: SOIC 150 mil and SOIC 300 mil
8L, 14L, 16L (DCG packages)
16L, 18L, 20L, 24L, 28L (PSG packages)

Assembly Material: See Table below

Description	Existing	Add
Assembly Location	ATP, OSEP, AIT	MMT
Assembly Materials	Die Attach: Ablestik 8290	2200D
	Wire: 1.0 Au	Au
	Mold Compound: EME-G600	G600
	Lead Frame: Copper Alloy	Lead Frame: Copper Alloy
	Plating: Sn	Plating: Sn

Qualification Test Results:

Test Vehicles: 16L SOIC 150 mil (1 lot) and 28L SOIC 300 mil (1 lot)

Test Description	Test Method	Test Results (SS/Rej)	
		SOIC 150 mil	SOIC 300 mil
* Temperature Cycling (Cond C, 500 cycles)	JESD22-A104	45/0	77/0
Auto Clave (121°C, 100% RH, 96 hours)	JESD22-A102	45/0	77/0
HAST (130°C, 85% RH, 96 hours)	JESD22-A110	NA	77/0

Notes: * Test requires moisture pre-conditioning sequence per JESD22-A113.



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA - 95138

PRODUCT/PROCESS CHANGE NOTICE (PCN)

ATTACHMENT I - PCN # : A0705-03

Tin Whisker Evaluation Test Data (JESD22A121 / JESD201)

Test Vehicle: SOIC-8L (3 lots)

Test Description	Test Condition	Test Duration	Spec Limits	Test Results (SS/Rej)
High Temperature / Humidity Storage	60°C / 87% RH	0, 1000, 2000, 3000 hours	< 40µm	6/0, 6/0, 6/0
Ambient Temperature / Humidity Storage	30°C / 60% RH	0, 1000, 2000, 3000 hours	< 40µm	6/0, 6/0, 6/0
Temperature Cycling	-55°C to +85°C	0, 500, 1000 cycles	< 40µm	6/0, 6/0, 6/0



PRODUCT/PROCESS CHANGE NOTICE (PCN)

ATTACHMENT I - PCN # : A0705-03

Qualification Information and Qualification Data:

GROUP 2:

Affected Packages: PLCC
28L, 32L, 44L, 52L, 68L, 84L (PLG packages)

Assembly Material: See Table below

Description	Existing	Add
Assembly Location	ATP, OSEP, AIT	MMT
Assembly Materials	Die Attach: 8361J	2200D
	Wire: 1.3mil Au	Au
	Mold Compound: EME-G600/C	G600
	Lead Frame: Copper Alloy	Lead Frame: Copper Alloy
	Plating: Sn	Plating: Sn

Qualification Test Results:

Test Vehicles: 68L PLCC (3 lots)

Test Description	Test Method	Test Results (SS/Rej)		
		Lot 1	Lot 2	Lot 3
* Temperature Cycling (Cond C, 500 cycles)	JESD22-A104	77/0	77/0	77/0
Auto Clave (121°C, 100% RH, 96 hours)	JESD22-A102	77/0	77/0	77/0
* HAST (130°C, 85% RH, 96 hours)	JESD22-A110	77/0	77/0	77/0

Notes: * Test requires moisture pre-conditioning sequence per JESD22-A113.



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA - 95138

PRODUCT/PROCESS CHANGE NOTICE (PCN)

ATTACHMENT I - PCN # : A0705-03

Tin Whisker Evaluation Test Data (JESD22A121 / JESD201)

Test Vehicle: SOIC-32L (3 lots)

Test Description	Test Condition	Test Duration	Spec Limits	Test Results (SS/Rej)
High Temperature / Humidity Storage	60°C / 87% RH	0, 1000, 2000, 3000 hours	< 40µm	6/0, 6/0, 6/0
Ambient Temperature / Humidity Storage	30°C / 60% RH	0, 1000, 2000, 3000 hours	< 40µm	6/0, 6/0, 6/0
Temperature Cycling	-55°C to +85°C	0, 500, 1000 cycles	< 40µm	6/0, 6/0, 6/0



PRODUCT/PROCESS CHANGE NOTICE (PCN)

ATTACHMENT II - PCN # : A0705-03

Affected Part Number

Part Number	Part Number	Part Number	Part Number
ICS1522MLF	IDT2308-1HDCGI	ICS2309M-1HLF	IDT23S09-1DCGI
ICS1523MLF	IDT2308-2DCG	ICS2309MI-1HLF	IDT23S09-1HDCG
ICS1524AMLF	IDT2308-2DCGI	IDT2309NZ-1HDCG	IDT23S09-1HDCGI
ICS1562BM-201-4LF	IDT2308-2HDCG	IDT2309NZ-1HDCGI	IDT23S09E-1DCG
ICS1562BM-201LF	IDT2308-2HDCGI	IDT23S05-1DCG	IDT23S09E-1HDCGI
ICS1574BMLF	IDT2308-3DCG	IDT23S05-1DCGI	IDT23S09T-1DCG
ICS1727M-07LF	IDT2308-3DCGI	IDT23S05-1HDCG	ICS2402MLF
ICS1727M-08LF	IDT2308-4DCG	IDT23S05-1HDCGI	ICS251M-01LF
ICS180M-01LF	IDT2308-4DCGI	IDT23S05E-1DCG	ICS251M-03LF
ICS180M-03LF	IDT2308-5HDCG	IDT23S05E-1DCGI	ICS251PMILF
ICS180M-51LF	IDT2308-5HDCGI	IDT23S05E-1HDCG	ICS251PMLF
ICS180M-52LF	IDT2308A-1DCG	IDT23S05E-1HDCGI	ICS252EM-01LF
ICS180M-53LF	IDT2308A-1DCGI	IDT23S05T-1DCG	ICS252M-01LF
ICS180MI-01LF	IDT2308A-1HDCG	IDT23S05T-1DCGI	ICS252M-04LF
ICS181M-01LF	IDT2308A-1HDCGI	IDT23S08-1DCG	ICS252M-05LF
ICS181M-02LF	IDT2308A-2DCG	IDT23S08-1DCGI	ICS252M-09LF
ICS181M-03LF	IDT2308A-2DCGI	IDT23S08-1HDCG	ICS252MI-09LF
ICS181M-51LF	IDT2308A-2HDCG	IDT23S08-1HDCGI	ICS252PMILF
ICS181M-52LF	IDT2308A-2HDCGI	IDT23S08-2DCG	ICS252PMLF
ICS181M-53LF	IDT2308A-3DCG	IDT23S08-2DCGI	ICS301M-28LF
ICS181MI-01LF	IDT2308A-3DCGI	IDT23S08-2HDCG	ICS307M-02ILF
ICS181MI-02LF	IDT2308A-4DCG	IDT23S08-2HDCGI	ICS307M-02LF
ICS2008BVLF	IDT2308A-4DCGI	IDT23S08-3DCG	ICS331M-26LF
IDT2305-1DCG	IDT2308A-5HDCG	IDT23S08-3DCGI	ICS332M-15LF
IDT2305-1DCGI	IDT2308A-5HDCGI	IDT23S08-4DCG	ICS332M-29LF
IDT2305-1HDCG	IDT2308B-1DCG	IDT23S08-4DCGI	ICS332M-32LF
IDT2305-1HDCGI	IDT2308B-1DCGI	IDT23S08-5HDCG	ICS332M-33LF
IDT2305A-1DCG	IDT2308B-1HDCG	IDT23S08-5HDCGI	ICS332M-49LF
IDT2305A-1DCGI	IDT2308B-1HDCGI	IDT23S08E-1DCG	ICS332M-54LF
IDT2305A-1HDCG	IDT2308B-2DCG	IDT23S08E-1DCGI	ICS332M-55LF
IDT2305A-1HDCGI	IDT2308B-2DCGI	IDT23S08E-1HDCG	ICS332M-63LF
IDT2305B-1DCG	IDT2308B-3DCG	IDT23S08E-1HDCGI	ICS332M-69LF
IDT2305B-1DCGI	IDT2308B-4DCG	IDT23S08E-2DCG	ICS333M-13LF
IDT2305B-1HDCG	IDT2309-1DCG	IDT23S08E-2DCGI	ICS341M-05LF
IDT2305B-1HDCGI	IDT2309-1DCGI	IDT23S08E-2HDCG	ICS341M-09LF
ICS2305M-1HLF	IDT2309-1HDCG	IDT23S08E-2HDCGI	ICS341M-14LF
ICS2305M-1LF	IDT2309-1HDCGI	IDT23S08E-3DCG	ICS341M-16LN
ICS2305MI-1HLF	IDT2309A-1DCG	IDT23S08E-3DCGI	ICS341M-23LF
ICS2305MI-1LF	IDT2309A-1DCGI	IDT23S08E-4DCG	ICS341M-25LF
IDT2305NZ-1HDCG	IDT2309A-1HDCG	IDT23S08E-4DCGI	ICS341M-27LF
IDT2305NZZ-1DCG	IDT2309A-1HDCGI	IDT23S08E-5HDCG	ICS341M-28LF
IDT2308-1DCG	IDT2309B-1DCG	IDT23S08E-5HDCGI	ICS341M-30LF
IDT2308-1DCGI	IDT2309B-1HDCG	IDT23S08T-1DCG	ICS341M-33LF
IDT2308-1HDCG	IDT2309B-1HDCGI	IDT23S09-1DCG	ICS341MI-18LF

Notes: For T & R (shipping method) "8", "T" and "R2" suffix is added to the IDT, ICS/MK and MPC/MC part# respectively.



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA - 95138

PRODUCT/PROCESS CHANGE NOTICE (PCN)

ATTACHMENT II - PCN # : A0705-03

Affected Part Number

Part Number	Part Number	Part Number	Part Number
ICS341MI-20LF	ICS343MI-45LF	ICS443MW-38LF	ICS553MILF
ICS341MI-24LF	ICS343MILF	ICS443MW-42LF	ICS553MLF
ICS341MI-26LF	ICS343MIPLF	ICS452M-02LF	ICS556M-04ILF
ICS341MI-28LF	ICS343MLF	IDT49FCT3805ASOG	ICS557M-01LF
ICS341MIPLF	ICS343MPLF	IDT49FCT3805ASOGI	ICS557MI-01LF
ICS341MLF	ICS3726M-02LF	IDT49FCT3805BSOG	ICS570AILF
ICS341MPLF	ICS3726MI-02LF	IDT49FCT3805BSOGI	ICS570ALF
ICS342M-02LF	ICS401M-60LF	IDT49FCT3805SOG	ICS570BILF
ICS342M-05LF	ICS409MLF	IDT49FCT3805SOGI	ICS570BLF
ICS342M-07LF	ICS411MLF	IDT49FCT805ASOG	ICS570MILF
ICS342M-11LF	ICS412M-01LF	IDT49FCT805ASOGI	ICS570MLF
ICS342M-12LF	ICS412M-02LF	IDT49FCT805BTSOG	ICS571MLF
ICS342M-13LF	ICS422M-01LF	IDT49FCT805CTSOG	ICS574MILF
ICS342M-14LF	ICS422M-02LF	IDT49FCT805SOG	ICS574MLF
ICS342M-15LF	ICS422M-03LF	IDT49FCT805SOGI	ICS580M-01ILF
ICS342M-16LF	ICS422M-15LF	IDT49FCT806ASOG	ICS580M-01LF
ICS342M-17LF	ICS4231M-03LF	IDT49FCT806SOG	IDT5991A-2JG
ICS342M-18LF	ICS431M-19LF	ICS501AMILF	IDT5991A-5JGI
ICS342M-20LF	ICS431M-31LF	ICS501AMLF	IDT5991A-7JGI
ICS342M-23LF	ICS432M-70LF	ICS501MILF	ICS5V10004PSGI
ICS342M-24LF	ICS433M-47LF	ICS501MLF	IDT5V30002DCG
ICS342M-26LF	ICS433M-65LF	ICS502MILF	IDT5V50009DCG
ICS342M-28LF	ICS441M-01LF	ICS502MLF	IDT5V5201DCGI
ICS342M-29LF	ICS441M-06LF	ICS503MLF	IDT5V5206DCGI
ICS342M-30LF	ICS441M-08LF	ICS507M-01ILF	IDT5V551DCGI
ICS342M-32LF	ICS441M-17LF	ICS507M-01LF	IDT5V7860DCG
ICS342MI-26LF	ICS441M-22LF	ICS511MILF	IDT5V9881DCGI
ICS342MI-28LF	ICS441M-25LF	ICS511MLF	IDT5V9883DCGI
ICS342MI-32LF	ICS441MI-24LF	ICS512MILF	IDT5V9910A-2SOG
ICS342MIPLF	ICS442M-13LF	ICS512MLF	IDT5V9910A-5SOGI
ICS342MLF	ICS442M-18LF	ICS513MLF	IDT5V9910A-7SOGI
ICS342MPLF	ICS442M-22LF	ICS514AMLF	IDT5V991A-2JG
ICS343M-09LF	ICS443M-07LF	ICS514MLF	IDT5V991A-2JGI
ICS343M-24LF	ICS443M-20LF	ICS524MILF	IDT5V991A-5JGI
ICS343M-25LF	ICS443M-33LF	ICS542MILF	IDT5V991A-7JGI
ICS343M-32LF	ICS443M-37LF	ICS542MLF	IDT5V994JGI
ICS343M-39LF	ICS443M-41LF	ICS544MI-01LF	ICS601M-01ILF
ICS343M-40LF	ICS443M-43LF	ICS548AM-03LF	ICS601M-01LF
ICS343M-44LF	ICS443M-46LF	ICS548AMI-03LF	ICS601M-02ILF
ICS343MI-14LF	ICS443MI-42LF	ICS548MI-03LF	IDT6116LA15SOG
ICS343MI-23LF	ICS443MW-23LF	ICS551AMILF	IDT6116LA15SOGI
ICS343MI-31LF	ICS443MW-28LF	ICS551MILF	IDT6116LA20SOG
ICS343MI-36LF	ICS443MW-35LF	ICS551MLF	IDT6116LA20SOGI
ICS343MI-42LF	ICS443MW-36LF	ICS551MLN	IDT6116LA25SOG

Notes: For T & R (shipping method) "8", "T" and "R2" suffix is added to the IDT, ICS/MK and MPC/MC part# respectively.



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA - 95138

PRODUCT/PROCESS CHANGE NOTICE (PCN)

ATTACHMENT II - PCN # : A0705-03

Affected Part Number

Part Number	Part Number	Part Number	Part Number
IDT6116LA25SOGI	IDT6V10010SOGI	IDT7130SA55JG	ICS7151AM-50LF
IDT6116LA35SOG	IDT6V30003DCG	IDT71321LA20JG	ICS7151AMI-50LF
IDT6116LA35SOGI	IDT6V40001DCGW2	IDT71321LA25JGI	ICS7151M-10LF
IDT6116LA45SOG	IDT7005L15JG	IDT71321LA55JG	ICS7151M-20LF
IDT6116LA45SOGI	IDT7005L20JG	IDT71321SA25JG	ICS7151M-40LF
IDT6116SA15SOG	IDT7005L20JGI	IDT71321SA55JG	ICS7151M-50LF
IDT6116SA15SOGI	IDT7005L35JG	IDT71321SA55JGI	ICS7151MI-10LF
IDT6116SA20SOG	IDT7005S25JG	IDT7132LA20JG	ICS7151MI-20LF
IDT6116SA20SOGI	IDT7005S35JG	IDT7132LA25JG	ICS7151MI-40LF
IDT6116SA25SOG	IDT7006L15JG	IDT7132LA25JGI	ICS7151MI-50LF
IDT6116SA25SOGI	IDT7006L20JGI	IDT7132LA35JG	ICS7152AM-02LF
IDT6116SA35SOG	IDT7007L15JG	IDT7132LA55JG	ICS7152AM-11LF
IDT6116SA35SOGI	IDT7007L20JGI	IDT7132SA35JG	ICS7152AMI-02LF
IDT6116SA45SOG	IDT7008L15JG	IDT7132SA55JG	ICS7152AMI-11LF
IDT6116SA45SOGI	IDT70121L25JG	IDT7133LA20JG	ICS7152M-01LF
ICS613MLF	IDT70121L55JG	IDT7133LA25JG	ICS7152M-02LF
ICS620M-21LF	IDT7014S12JG	IDT7133LA25JGI	ICS7152M-11LF
ICS621MILF	IDT7014S15JG	IDT7133SA20JG	ICS7152M-12LF
ICS621MLF	IDT7024L15JG	IDT7133SA25JG	ICS7152MI-01LF
ICS633MLF	IDT7024L20JGI	IDT7133SA35JG	ICS7152MI-02LF
ICS650AM-53LF	IDT7025L15JG	IDT7133SA55JG	ICS7152MI-11LF
ICS650M-38LF	IDT7025L20JGI	IDT7133SA70JG	ICS7152MI-12LF
ICS650M-53LF	IDT7025S35JG	IDT71342LA20JG	IDT71V321L25JG
ICS650MI-46LF	IDT7025S55JG	IDT71342LA25JGI	IDT71V321L35JGI
ICS650MI-53LF	IDT7026L15JG	IDT71342LA35JG	IDT7200L12JG
ICS651BMLF	IDT70V05L15JG	IDT71342SA35JG	IDT7200L15JGI
ICS651MILF	IDT70V05L20JGI	IDT71342SA55JG	IDT7201LA12JG
ICS651MLF	IDT70V07L20JG	IDT7134LA20JG	IDT7201LA15JG
ICS662M-03LF	IDT70V24L15JG	IDT7134LA25JG	IDT7201LA15JGI
ICS663MILF	IDT70V24S35JGI	IDT7134LA25JGI	IDT7201LA20JG
ICS663MLF	IDT70V25L15JG	IDT7134LA35JG	IDT7201LA25JG
ICS667M-01LF	IDT70V25L20JGI	IDT7134LA55JG	IDT7201LA25JGI
ICS670M-01ILF	IDT70V26L25JG	IDT7134SA25JG	IDT7201LA35JG
ICS670M-01LF	IDT71256SA12SOG1	IDT7134SA55JG	IDT7201LA50JG
ICS670M-02LF	IDT71256SA15SOG1	IDT7140LA20JG	IDT7202L15JG
ICS670M-03ILF	IDT71256SA20SOG1	IDT7140LA25JGI	IDT7202L20JG
ICS670M-04ILF	IDT71256SA35SOG1	IDT7140SA55JG	IDT7202L25JG
ICS670MI-02LF	IDT71256SA55SOG1	IDT71421LA20JG	IDT7202L35JG
ICS671M-01LF	IDT7130LA20JG	IDT7142LA20JG	IDT7202L50JG
ICS671M-03ILF	IDT7130LA25JG	IDT7143LA20JG	IDT7202LA12JG
ICS672M-01LF	IDT7130LA25JGI	IDT7143LA25JGI	IDT7202LA15JG
ICS672M-02LF	IDT7130LA55JG	ICS7150M-01LF	IDT7202LA15JGI
ICS673M-01ILF	IDT7130SA25JG	ICS7150MLF	IDT7202LA20JG
ICS673M-01LF	IDT7130SA35JG	ICS7151AM-10LF	IDT7202LA25JG

Notes: For T & R (shipping method) "8", "T" and "R2" suffix is added to the IDT, ICS/MK and MPC/MC part# respectively.



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA - 95138

PRODUCT/PROCESS CHANGE NOTICE (PCN)

ATTACHMENT II - PCN # : A0705-03

Affected Part Number

Part Number	Part Number	Part Number	Part Number
IDT7202LA25JGI	IDT72251L10JG	IDT74FCT240ATSOG	IDT74FCT621ATSOG
IDT7202LA35JG	ICS722MLF	IDT74FCT240CTSOG	IDT74FCT621TSOG
IDT7202LA50JG	IDT72403L45SOG	IDT74FCT244ASOG	IDT74FCT807BTSOG
IDT7203L12JG	IDT72413L25SOG	IDT74FCT244ATSOG	IDT74FCT807BTSOGI
IDT7203L15JG	IDT72421L10JG	IDT74FCT244CSOG	IDT74FCT807CTSOG
IDT7203L15JGI	IDT72615L20JG	IDT74FCT244CTSOG	IDT74FCT807CTSOGI
IDT7203L20JG	IDT728980JG	IDT74FCT245ATSOG	IDT74FCT810BTSOG
IDT7203L25JGI	IDT728981JG	IDT74FCT245CTSOG	IDT74FCT810CTSOG
IDT7203L35JG	IDT728985JG	IDT74FCT257ATSOG	IDT74FCT823ATSOG
IDT7203L50JG	ICS728MLF	IDT74FCT257CTSOG	IDT74FCT823CTSOG
IDT7204L12JG	IDT7290820JG	IDT74FCT257DTSOG	IDT74FCT88915TTAJG
IDT7204L15JG	IDT72V01L15JG	IDT74FCT273ATSOG	IDT74FCT88915TTBJG
IDT7204L15JGI	IDT72V01L25JG	IDT74FCT273CTSOG	IDT74FCT88915TTCJG
IDT7204L20JG	IDT72V01L25JGI	IDT74FCT3244ASOG	IDT74FCT88915TTDJG
IDT7204L25JG	IDT72V01L35JG	IDT74FCT3244SOG	IDT74LVC244ASOG
IDT7204L35JG	IDT72V02L15JG	IDT74FCT373ATSOG	IDT74LVC245ASOG
IDT7204L50JG	IDT72V02L25JGI	IDT74FCT373CTSOG	IDT74LVC4245ASOG
IDT7205L12JG	IDT72V03L15JG	IDT74FCT374ATSOG	IDT74LVCC3245ASOG
IDT7205L15JG	IDT72V03L25JG	IDT74FCT374CTSOG	IDT79R3041-20JG
IDT7205L15JGI	IDT72V03L25JGI	IDT74FCT377ATSOG	IDT79R3041-25JG
IDT7205L20JG	IDT72V03L35JG	IDT74FCT377CTSOG	IDT79R3041-33JG
IDT7205L25JG	IDT72V04L15JG	IDT74FCT377DTSOG	IDT821004JG
IDT7205L35JG	IDT72V04L25JG	IDT74FCT38072DCGI	IDT821024JG
IDT7206L15JG	IDT72V04L25JGI	IDT74FCT38074DCGI	ICS83021AMILF
IDT7206L25JG	IDT72V04L35JG	IDT74FCT38075DCGI	ICS83023AMILF
IDT7207L15JG	IDT72V05L15JG	IDT74FCT3807ASOG	ICS83026AMILF
IDT7207L20JGI	IDT72V05L25JGI	IDT74FCT3807ASOGI	ICS83026BMI-01LF
IDT7208L20JG	IDT72V06L15JG	IDT74FCT3807SOG	ICS8302AM-01LF
IDT7208L25JGI	IDT72V06L25JGI	IDT74FCT3807SOGI	ICS8302AMI-01LF
ICS721MLF	IDT72V221L10JG	IDT74FCT388915TBJG	ICS8302AMILF
IDT72201L10JG	IDT72V241L10JG	IDT74FCT388915TCJG	ICS8302AMLF
IDT72201L15JG	IDT72V241L20JG	IDT74FCT388915TDJG	ICS8304AM-01LF
IDT72201L15JGI	IDT72V251L10JG	IDT74FCT388915TEJG	ICS8304AMILF
IDT72201L25JG	IDT72V8980JG	IDT74FCT521ATSOG	ICS8304AMLF
IDT7221L10JG	IDT72V8981JG	IDT74FCT521CTSOG	ICS8304AMLN
IDT7221L12JGI	IDT72V8985JG	IDT74FCT540ATSOG	ICS83905AMLF
IDT72215LB10JG	IDT72V90823JG	IDT74FCT540CTSOG	ICS840031AMILF
IDT72221L10JG	IDT74FCT157ATSOG	IDT74FCT543ATSOG	ICS840AM-125LF
IDT72221L25JG	IDT74FCT157CTSOG	IDT74FCT543CTSOG	ICS840AM-275LF
IDT72225LB10JG	IDT74FCT157DTSOG	IDT74FCT543DTSOG	ICS840AM-75LF
IDT72231L10JG	IDT74FCT2244ATSOG	IDT74FCT573ATSOG	ICS8431AM-21LF
IDT72235LB10JG	IDT74FCT2244CTSOG	IDT74FCT573CTSOG	ICS8431EM-11LF
IDT72241L10JG	IDT74FCT2245ATSOG	IDT74FCT574ATSOG	ICS843241AM-100LF
IDT72241L15JG	IDT74FCT2245CTSOG	IDT74FCT574CTSOG	ICS843241AM-150LF

Notes: For T & R (shipping method) "8", "T" and "R2" suffix is added to the IDT, ICS/MK and MPC/MC part# respectively.



PRODUCT/PROCESS CHANGE NOTICE (PCN)

ATTACHMENT II - PCN # : A0705-03

Affected Part Number

Part Number	Part Number	Part Number	Part Number
ICS843241AM-300LF	ICS85411AMILF	ICS9159C-02CW28LF	MK1707SLF
ICS843241AM-75LF	ICS85411AMLF	ICS9159M-05LF	MK1709SLF
ICS843241BM-100LF	ICS87021AMILF	ICS9161A-01CW16LF	MK1721-02SLF
ICS843241BM-150LF	ICS8725AM-21LF	ICS9169CM-23LF	MK1726-01SLF
ICS843241BM-300LF	ICS873033AMLF	ICS9169M-01LF	MK1726-08SLF
ICS843241BM-75LF	ICS87332AMI-01LF	ICS9170-01CS08LF	MK1727-03AMLF
ICS843246AMILF	ICS87339AM-01LF	ICS9170-02CS08LF	MK1728-01SLF
ICS84325EMLN	ICS87339AMI-11LF	ICS9170-04CS08LF	MK1728AM-01LF
ICS84329AM-01LF	ICS87354AMILF	ICS91718BMLF	MK2049-34SAILF
ICS84329AV-01LF	ICS8735AM-21LF	ICS91718CMLF	MK2049-36SILF
ICS84329AVLF	ICS8735AMI-21LF	ICS9172-01CW16LF	MK2049-45ASILF
ICS84329BM-01LF	ICS873S02BMILF	ICS9173-01CS08LF	MK2049-45SILF
ICS84329BV-01LF	ICS87421AMILF	ICS9173-15CS08LF	MK2058-01SILF
ICS84329BVLF	ICS8745BM-21LF	ICS91730AMLF	MK2059-01SILF
ICS84330AV-02LF	ICS8745BMI-21LF	ICS9179AM-12LF	MK2302S-01ILF
ICS84330CV-01LF	ICS874S02BMILF	MC100ES6011EF	MK2302S-01LF
ICS84330CVLN	ICS9107C-05CS08LF	MC100ES6017EG	MK2304S-1ILF
ICS843AM-125LF	ICS9107C-10CS08LF	MC100ES6030EG	MK2304S-1LF
ICS84427CMLF	ICS9107C-17CS08LF	MC100ES6039EG	MK2304S-2LF
ICS85211AMI-01LF	ICS9110-01CS14LF	MC100ES6056EG	MK2308S-1HILF
ICS85211AMI-03LF	ICS9110-02CS14LF	MC100ES60T23EF	MK2308S-1HLF
ICS85211AMILF	ICS9112AM-16LF	MC100ES8011HEF	MK2308S-2ILF
ICS85211BMI-03LN	ICS9112AM-16LN	MC100ES8011PEF	MK2308S-2LF
ICS85222AM-01LF	ICS9112AM-17LF	MC88915EI55	MK2703BSILF
ICS85222AM-02LF	ICS9112AM-26LF	MC88915EI70	MK2703BSLF
ICS85222AMLF	ICS9112AM-27LF	MC88915TEI100	MK2703SILF
ICS852911AVILF	ICS9112AM-28LF	MC88915TEI133	MK2703SLF
ICS853001AMLF	ICS9112BM-17LF	MC88915TEI160	MK2704SLF
ICS853011BMLF	ICS9112CM-18LF	MC88915TEI55	MK2705SLF
ICS853011CMLF	ICS9112M-07LF	MC88915TEI70	MK2712SLF
ICS853013AMLF	ICS9112M-22LF	MC88916EG70	MK2716SLF
ICS853016AMLF	ICS9112M-41LF	MC88916EG80	MK2727SLF
ICS853111AV-01LF	ICS91305AMILF	MC88920EG	MK2745-21SLF
ICS85311AMLF	ICS91305AMLF	MC88LV915TEI	MK2745-24SLF
ICS85314BMI-01LF	ICS91309AMILF	MC88LV926EG	MK2745-26SLF
ICS85320AMILF	ICS91309AMLF	MK1413SLF	MK2761ASLF
ICS85322AMILF	ICS91315BMLF	MK1491-06SLF	MK2772-01SLF
ICS85322AMLF	ICS9148AM-60LF	MK1574-01BSILF	MK3200SILF
ICS853310AVLF	ICS9154A-04CS16LF	MK1574-01SILF	MK3200SLF
ICS8534AMI-13LF	ICS9154A-10CS16LF	MK1574-01SLF	MK3711DMILF
ICS8534BMI-13LF	ICS9154A-27CS16LF	MK1704ALF	MK3711DMLF
ICS85356AMILF	ICS9154A-43CS16LF	MK1705ALF	MK3712DLF
ICS853L022AMLF	ICS9155C-01CW20LF	MK1707DLF	MK3720DLF
ICS853P022AMLF	ICS9155C-23CW20LF	MK1707SILF	MK3721DLF

Notes: For T & R (shipping method) "8", "T" and "R2" suffix is added to the IDT, ICS/MK and MPC/MC part# respectively.



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA - 95138

PRODUCT/PROCESS CHANGE NOTICE (PCN)

ATTACHMENT II - PCN # : A0705-03

Affected Part Number

Part Number	Part Number	Part Number	Part Number
MK3727CLF	MK5818SLF	MPC962305EF-1H	IDTQS3390SOG
MK3727DLF	MK712SILF	MPC962308EF-1H	IDTQS3VH125S1G
MK3727HLF	MK712SLF	MPC962309EF-1H	IDTQS3VH126S1G
MK3727SLF	MK9170-01CS08LF	ICSNIS/RC-872LF	IDTQS3VH245SOG
MK3732-10SLF	MK9170-02CS08LF	ICSNV021AMLF	IDTQS3VH257S1G
MK3734SLF	MK9170-05CS08LF	IDTNW6006ASG	IDTQS5917T-100TJG
MK3741SLF	MK9173-01CS08LF	ICSPIX84AMLF	IDTQS5917T-132TJG
MK3754BLF	MK9173-15CS08LF	IDTQS3125S1G	IDTQS5917T-70TJG
MK3754DLF	MPC905EF	IDTQS3126S1G	IDTQS5LV919-100JG
MK3754SLF	MPC9229EI	IDTQS3244SOG	IDTQS5LV919-133JG
MK5811ASLF	MPC9230EI	IDTQS3245SOG	IDTQS5LV919-160JG
MK5811BMLF	MPC9239EI	IDTQS3251S1G	IDTUS8032DCG
MK5811SLF	MPC92429EI	IDTQS3253S1G	ICSVS330DCG
MK5812SLF	MPC92439EI	IDTQS3257S1G	
MK5814SLF	MPC94551EF	IDTQS3306AS1G	

Notes: For T & R (shipping method) "8", "T" and "R2" suffix is added to the IDT, ICS/MK and MPC/MC part# respectively.