

---

# PRODUCT CHANGE NOTICE

**Data Sheet Electrical Specification  
Change for Intersil ISL62881\* and  
ISL62881B\* Products**

**Refer to:  
PCN11028**

**Date: March 9, 2011**

March 9, 2011

To: Our Valued Intersil Customer

Subject: **Data Sheet Electrical Specification Change for Intersil ISL62881\* and ISL62881B\* Products**

This notice is to inform you that Intersil has changed the data sheet electrical specification for the listed ISL62881\* and ISL62881B\* products. The removal of the IMON Output Current (ISUM @ 5  $\mu$ A) minimum and maximum limits is necessary to maintain product manufacturability in support of customer delivery requirements. The updated data sheet is available on the Intersil web site at <http://www.intersil.com/data/fn/fn6924.pdf>.

Products affected:

ISL62881HRTZ      ISL62881HRTZ-T      ISL62881BHRTZ      ISL62881BHRTZ-T

The data sheet electrical specification changes are as follows:

Parameter	Test Conditions	Current Limits			New Limits			Units
		Min	Typ	Max	Min	Typ	Max	
IMON Output Current	ISUM- pin current = 5 $\mu$ A	22	30	37.5	-	30	-	$\mu$ A

There will be no change in external marking of the packaged parts. Parts affected by this change are identifiable via Intersil's internal traceability system.

Intersil will take all necessary actions to conform to agreed upon customer requirements and to ensure the continued high quality and reliability of Intersil products being supplied. Customers may expect to receive product electrically screened to the revised data sheet beginning *ninety* days from the date of this notification or earlier with approval.

If you have concerns with this notice, Intersil must hear from you promptly. Please contact the nearest Intersil Sales Office or call the Intersil Corporate line at 1-888-468-3774, in the United States, or 1-321-724-7143 outside of the United States.

Regards,



Jon Brewster  
Intersil Corporation

PCN11028

CC: J. Touvell    D. Grener    M. Kafi