

Product Lifecycle Notice

Subject: Product Discontinuance / Obsolescence Notification

Publication Date: 2/15/2017

Revision Description:

Initial release

You are hereby provided notice that the Intersil products included on the attached parts list are being discontinued. As a valued customer, and one that has previously purchased one or more of such parts, Intersil Corporation is pleased to offer you a final life-of-type procurement for these parts. Recognizing that you will need some time to analyze your requirements, Intersil will accept orders for these products through the LTB (Life of Type Buy) / WITHDRAWN date provided in the attached list. All shipments under such orders shall be scheduled no later than the SHIP / OBSOLETE date provided. Intersil will attempt to honor all such purchase orders and scheduled delivery dates, but reserves the right to not accept new orders or to cancel existing orders if such orders cannot be filled through reasonable commercial effort.

Please review the list on the following pages and make adjustments as necessary in your database.

The information contained herein is intended for the recipients use only. Please limit the distribution of this material to those individuals within your immediate organization having a need to act upon the information.

If you are considering a redesign, and require assistance, please contact your local Sales or Rep office, or the Intersil Corporate Line, 1-888-468-3774, for our Central Applications Department.

Regards,



Jeffrey Touvell

Intersil Corporation

Exact Intersil Part # No other variation is being impacted.	Notice PLC17007 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
EL9112ILZ	15-Feb-17	15-Feb-17	15-Feb-17	ISL59913IRZ
EL9112ILZS2714	15-Feb-17	15-Feb-17	15-Feb-17	ISL59913IRZ
EL9112ILZ-T13	15-Feb-17	15-Feb-17	15-Feb-17	ISL59913IRZ-T7
EL9112ILZ-T13S2714	15-Feb-17	15-Feb-17	15-Feb-17	ISL59913IRZ-T7
EL9112ILZ-T7	15-Feb-17	15-Feb-17	15-Feb-17	ISL59913IRZ-T7
EL9112ILZ-T7S2714	15-Feb-17	15-Feb-17	15-Feb-17	ISL59913IRZ-T7
HDO-82C50AB6092-6	15-Feb-17	15-Aug-17	15-Feb-18	None
HIP4080AIB	15-Feb-17	15-Aug-17	15-Feb-18	HIP4080AIBZ
HIP4080AIBT	15-Feb-17	15-Aug-17	15-Feb-18	HIP4080AIBZT
HIP4080AIP	15-Feb-17	15-Aug-17	15-Feb-18	HIP4080AIPZ
HIP4081AIB	15-Feb-17	15-Aug-17	15-Feb-18	HIP4081AIBZ
HIP4081AIBT	15-Feb-17	15-Aug-17	15-Feb-18	HIP4081AIBZT
HIP4082IB	15-Feb-17	15-Aug-17	15-Feb-18	HIP4082IBZ
HIP4082IBT	15-Feb-17	15-Aug-17	15-Feb-18	HIP4082IBZT
HIP4086AB	15-Feb-17	15-Aug-17	15-Feb-18	HIP4086ABZ
HIP4086ABT	15-Feb-17	15-Aug-17	15-Feb-18	HIP4086ABZT
HSP45102SI-3396	15-Feb-17	15-Aug-17	15-Feb-18	None
HSP50214BVC	15-Feb-17	15-Aug-17	15-Feb-18	HSP50214BVCZ
HSP50214BVI	15-Feb-17	15-Aug-17	15-Feb-18	HSP50214BVIZ
HSP50415VI	15-Feb-17	15-Aug-17	15-Feb-18	HSP50415VIZ
ICL7660ACBA	15-Feb-17	15-Aug-17	15-Feb-18	ICL7660ACBAZA
ICL7660ACBA-T	15-Feb-17	15-Aug-17	15-Feb-18	ICL7660ACBAZA-T
ICL7660ACPA	15-Feb-17	15-Aug-17	15-Feb-18	ICL7660ACPAZ
ICL7660CPA	15-Feb-17	15-Aug-17	15-Feb-18	ICL7660CPAZ
ICL7660AIBA	15-Feb-17	15-Aug-17	15-Feb-18	ICL7660AIBAZA
ICL7660AIBA-T	15-Feb-17	15-Aug-17	15-Feb-18	ICL7660AIBAZA-T
ICL7660CBA	15-Feb-17	15-Aug-17	15-Feb-18	ICL7660CBAZ
ICL7660CBA-T	15-Feb-17	15-Aug-17	15-Feb-18	ICL7660CBAZ-T
ICL7660SCBA	15-Feb-17	15-Aug-17	15-Feb-18	ICL7660SCBAZ
ICL7660SCBA-T	15-Feb-17	15-Aug-17	15-Feb-18	ICL7660SCBAZ-T
ICL7660SCPA	15-Feb-17	15-Aug-17	15-Feb-18	ICL7660SCPAZ
ICL7660SIPA	15-Feb-17	15-Aug-17	15-Feb-18	ICL7660SIPAZ
ICL7660SIBA	15-Feb-17	15-Aug-17	15-Feb-18	ICL7660SIBAZ
ICL7660SIBAT	15-Feb-17	15-Aug-17	15-Feb-18	ICL7660SIBAZT
ICL7667CPA	15-Feb-17	15-Aug-17	15-Feb-18	ICL7667CPAZ
ICM7245AIM44Z	15-Feb-17	15-Aug-17	15-Feb-18	ICM7245BIM44Z
ICM7245AIM44ZT	15-Feb-17	15-Aug-17	15-Feb-18	ICM7245BIM44ZT
ISL1534IRZ	15-Feb-17	15-Aug-17	15-Feb-18	None
ISL1534IRZ-T13	15-Feb-17	15-Aug-17	15-Feb-18	None
ISL21070CIH320Z-TK	15-Feb-17	15-Aug-17	15-Feb-18	None
ISL21070CIH325Z-TK	15-Feb-17	15-Aug-17	15-Feb-18	None
ISL22317UFRTZ	15-Feb-17	15-Aug-17	15-Feb-18	ISL22317WFR TZ
ISL22317UFRTZ-TK	15-Feb-17	15-Aug-17	15-Feb-18	ISL22317WFR TZ-TK
ISL22343WFR20Z	15-Feb-17	15-Aug-17	15-Feb-18	none
ISL22343WFR20Z-TK	15-Feb-17	15-Aug-17	15-Feb-18	none
ISL22343WV20Z	15-Feb-17	15-Aug-17	15-Feb-18	none
ISL22343WV20Z-TK	15-Feb-17	15-Aug-17	15-Feb-18	none
ISL22414WV10Z-T7A	15-Feb-17	15-Aug-17	15-Feb-18	none
ISL22414WV10Z-TK	15-Feb-17	15-Aug-17	15-Feb-18	none
ISL22511WFB8Z	15-Feb-17	15-Aug-17	15-Feb-18	none
ISL22511WFB8Z-TK	15-Feb-17	15-Aug-17	15-Feb-18	none
ISL22511WFRU10Z-TK	15-Feb-17	15-Aug-17	15-Feb-18	none
ISL22512WFB8Z	15-Feb-17	15-Aug-17	15-Feb-18	none
ISL22512WFB8Z-TK	15-Feb-17	15-Aug-17	15-Feb-18	none
ISL43L420IRZ	15-Feb-17	15-Aug-17	15-Feb-18	None
ISL43L840IRZ	15-Feb-17	15-Aug-17	15-Feb-18	None
ISL43L840IRZ-T	15-Feb-17	15-Aug-17	15-Feb-18	None
ISL43L840IVZ	15-Feb-17	15-Aug-17	15-Feb-18	None
ISL43L840IVZ-T	15-Feb-17	15-Aug-17	15-Feb-18	None
ISL43L420IRZ-T	15-Feb-17	15-Aug-17	15-Feb-18	None
ISL43L841IRZ	15-Feb-17	15-Aug-17	15-Feb-18	None
ISL43L841IRZ-T	15-Feb-17	15-Aug-17	15-Feb-18	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC17007 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL5314IN	15-Feb-17	15-Aug-17	15-Feb-18	ISL5314INZ
ISL53562IA-TR5261	15-Feb-17	15-Aug-17	15-Feb-18	None
ISL53570IQZR5267	15-Feb-17	15-Aug-17	15-Feb-18	None
ISL59119IBZ-EVALZ	15-Feb-17	15-Aug-17	15-Feb-18	None
ISL59481EVAL1Z	15-Feb-17	15-Aug-17	15-Feb-18	None
ISL59483EVAL1Z	15-Feb-17	15-Aug-17	15-Feb-18	None
ISL59532IK-EVAL	15-Feb-17	15-Aug-17	15-Feb-18	None
ISL59534IKEZ-EVAL	15-Feb-17	15-Aug-17	15-Feb-18	None
ISL6236IRZAR5281	15-Feb-17	15-Aug-17	15-Feb-18	None
ISL6236IRZA-TKR5281	15-Feb-17	15-Aug-17	15-Feb-18	None
ISL6236IRZA-TR5281	15-Feb-17	15-Aug-17	15-Feb-18	None
ISL6328ACRZ	15-Feb-17	15-Aug-17	15-Feb-18	None
ISL6328ACRZ-T	15-Feb-17	15-Aug-17	15-Feb-18	None
ISL6334ACRZ-TS2490	15-Feb-17	15-Aug-17	15-Feb-18	None
ISL6406MVPE	15-Feb-17	15-Aug-17	15-Feb-18	None
ISL6406MVPE-TK	15-Feb-17	15-Aug-17	15-Feb-18	None
ISL70003SEHF/PROTO	15-Feb-17	15-Aug-17	15-Feb-18	ISL70003SEHFE/PROTO
ISL70003SEHFE/PROTO	15-Feb-17	15-Aug-17	15-Feb-18	ISL70003SEHFE/PROTO
ISL70003SEHVF	15-Feb-17	15-Aug-17	15-Feb-18	ISL70003ASEHVFE
ISL70003SEHVFE	15-Feb-17	15-Aug-17	15-Feb-18	ISL70003ASEHVFE
ISL70003SEHVFES2745	15-Feb-17	15-Aug-17	15-Feb-18	ISL70003ASEHVFE
ISL70003SEHVX	15-Feb-17	15-Aug-17	15-Feb-18	ISL70003ASEHVX
ISL70003SEHVXS2745	15-Feb-17	15-Aug-17	15-Feb-18	ISL70003ASEHX/SAMPLE
ISL70003SEHX/SAMPLE	15-Feb-17	15-Aug-17	15-Feb-18	ISL70003ASEHX/SAMPLE
ISL78200AVEZ	15-Feb-17	15-Aug-17	15-Feb-18	ISL78201AVEZ
ISL78200AVEZ-T	15-Feb-17	15-Aug-17	15-Feb-18	ISL78201AVEZ-T
ISL78200AVEZ-TR5506	15-Feb-17	15-Aug-17	15-Feb-18	ISL78201AVEZ-TR5506
ISL78205AVEZ	15-Feb-17	15-Aug-17	15-Feb-18	ISL78206AVEZ
ISL78205AVEZ-T	15-Feb-17	15-Aug-17	15-Feb-18	ISL78206AVEZ-T
ISL78205AVEZ-TR5506	15-Feb-17	15-Aug-17	15-Feb-18	ISL78206AVEZ-TR5506
ISL8200AMMREP	15-Feb-17	15-Aug-17	15-Feb-18	None
ISL8200AMMREP-T	15-Feb-17	15-Aug-17	15-Feb-18	None
ISL83699IRZ	15-Feb-17	15-Aug-17	15-Feb-18	None
ISL83699IRZ-T	15-Feb-17	15-Aug-17	15-Feb-18	None
ISL84782IRZ	15-Feb-17	15-Aug-17	15-Feb-18	None
ISL84782IRZ-T	15-Feb-17	15-Aug-17	15-Feb-18	None
ISL8499IRTZ	15-Feb-17	15-Aug-17	15-Feb-18	None
ISL8499IRTZ-T	15-Feb-17	15-Aug-17	15-Feb-18	None
ISL8499IRZ	15-Feb-17	15-Aug-17	15-Feb-18	None
ISL8499IRZ-T	15-Feb-17	15-Aug-17	15-Feb-18	None
ISL8499IVZ	15-Feb-17	15-Aug-17	15-Feb-18	None
ISL8499IVZ-T	15-Feb-17	15-Aug-17	15-Feb-18	None
ISL90726UIE627Z-TK	15-Feb-17	15-Aug-17	15-Feb-18	ISL90727WIE627Z-TK
ISL90810UAU8Z	15-Feb-17	15-Aug-17	15-Feb-18	none
ISL90810UAU8Z-TK	15-Feb-17	15-Aug-17	15-Feb-18	none
ISL90810UIU8Z	15-Feb-17	15-Aug-17	15-Feb-18	none
ISL90810UIU8Z-TK	15-Feb-17	15-Aug-17	15-Feb-18	none
ISL90841WIV1427Z	15-Feb-17	15-Aug-17	15-Feb-18	none
ISL90841WIV1427Z-TK	15-Feb-17	15-Aug-17	15-Feb-18	none
X93256UV14IZ-2.7	15-Feb-17	15-Aug-17	15-Feb-18	none
X93256UV14IZ-2.7T1	15-Feb-17	15-Aug-17	15-Feb-18	none
X93256WV14IZ-2.7	15-Feb-17	15-Aug-17	15-Feb-18	none
X93256WV14IZ-2.7T1	15-Feb-17	15-Aug-17	15-Feb-18	none