

To our customers,

---

## Old Company Name in Catalogs and Other Documents

---

On April 1<sup>st</sup>, 2010, NEC Electronics Corporation merged with Renesas Technology Corporation, and Renesas Electronics Corporation took over all the business of both companies. Therefore, although the old company name remains in this document, it is a valid Renesas Electronics document. We appreciate your understanding.

Renesas Electronics website: <http://www.renesas.com>

April 1<sup>st</sup>, 2010  
Renesas Electronics Corporation

Issued by: Renesas Electronics Corporation (<http://www.renesas.com>)

Send any inquiries to <http://www.renesas.com/inquiry>.

# MESC TECHNICAL NEWS

No. M16C-32-9908

## M16C/60 Series

### Precautions for Address Match Interrupt

#### 1. Related devices

M16C/60 Series

#### 2. Precautions

When using the address match interrupt, please observe the following usage conditions.

- (1) Address match interrupt for internal address.
- (2) Address match interrupt for external address and 16-bit bus.

When external address and 8-bit bus, you can not use the address match interrupt for external address.