

## Exclusively for design purposes! No part of this may be disclosed to a third party without the consent of NEC Electronics

Concerned Products:	Custome	er Notification	Date: April 16 <sup>th</sup> , 1998		
IE-780233-NS-EM4			NEC-Electronics (Europe) GmbH EAD – Technical Product Support		
	Bug	ı Report	Source Doc: SBG-T-1551, SBG-T-1546		
			Author: A. Wohlfahrt / W. Noll		
Date of initial issue:	Apr. 16 <sup>th</sup> , 99	Doc. No.:	TPS-LE-B-0T013		
1 <sup>st</sup> revision :		Doc. No.:	TPS-LE-B-0T013-1		
2 <sup>nd</sup> revision :		Doc. No.:	TPS-LE		

Exclusively for design purposes! No part of this may be disclosed to a third party without the consent of NEC Electronics

## (A) BUG LIST (1/2)

Bug	Outline	IE-780233-NS-EM4			
No.					
		V1.A	V1.B		
		Code "A"	Code "B"		
1	Modification accompanying the	W.S.	✓		
	IE-78K0-NS-P01 upgrade				

✓: No problem

Bug (will be corrected by next version upgrade)

**6**\*: Bug (restriction, not corrected by version upgrade)



Exclusively for design purposes! No part of this may be disclosed to a third party without the consent of NEC Electronics

## (B) BUG DESCRIPTION

Bug No.	Outline	Description
1	Modification accompanying the IE-78K0-NS-P01 upgrade	The modification is necessary in order to work with the upgraded version of the IE-78K0-NS-P01 low voltage operation bug.