

RENESAS TOOL NEWS on Sep. 1, 2008: 080901/tn10

Correction to The Supplementary Volume of User's Manual for E200F Emulator R0E0200F1EMU00 (used for the SH7286, SH7285 and SH7243)

We notify corrections to "SH-2A, SH-2 E200F Emulator Additional Document for User's Manual, Supplementary Information on Using the SH7286, SH7285 and SH7243." (This manual is dedicated to the E200F emulator R0E0200F1EMU00, which is used for the SH-2A and SH-2 CPUcored MCUs, SuperH RISC engine family.)

## 1. Document and Page Concerned

Page 21, Figure 2.11 in "SH-2A, SH-2 E200F Emulator Additional Document for User's Manual, Supplementary Information on Using the SH7286, SH7285 and SH7243" (Document No. REJ10J1662-0200)

## 2. Corrections

- (1) Delete SH7286 from the group names of SH7286, SH7285, and SH7243, which is written next to the top right of Figure 2.11.
- (2) So for an example of connection diagrams of the SH7286, refer to here.

The SH7286 group is different from the SH7285 and SH7243 groups in connection diagrams as follows:

SH7286: TRST is pulled down

through 1 kilo-ohm.

TDO is directly connected

without pull-up or

pull-down.

SH7285 and

TRST and TDO are pulled up

SH7243: through

4.7 kilo-ohms.

## [Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

 $\ @\ 2010\mbox{-}2016$  Renesas Electronics Corporation. All rights reserved.