

RENESAS TOOL NEWS on February 1, 2007: 070201/tn8

Corrections to Catalogs Published in October 2006

We notify corrections to the following catalogs:

- Renesas Quick Reference Guide to Semiconductor Devices,
Document No. REJ02A0003-0700 (Published in October 2006)
- Renesas MCU for In-Vehicle Networking,
Document No. REJ01B0002-0400 (Published in October 2006)

These corrections will be seen on here from February 20 on.

NOTICE: The above URL is that of our global site (in English).
The regional sites will be opened two or three days after the above date.

1. Correction to Renesas Quick Reference Guide to Semiconductor Devices,

Document No. REJ02A0003-0700 (Published in October 2006)

Page 84, body of the table; top in the License tool column
(at the right end)

Read HS7780KCU01SR for HS7770KCU01SR

2. Correction to Renesas MCU for In-Vehicle Networking,

Document No. REJ01B0002-0400 (Published in October 2006)

Page 63, body of the table; top in the License tool column
(at the right end)

Read HS7780KCU01SR for HS7770KCU01SR

3. Related Information

We notified a correction to this catalog in the following RENESAS TOOL NEWS.

- RENESAS TOOL NEWS "Corrections to Catalogs Published in October 2006" issued on October 16, 2006.

- RENESAS TOOL NEWS "Corrections to Catalogs Published in October 2006" issued on November 1, 2006.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.