

RENESAS TOOL NEWS on December 1, 2007: 071201/tn4

Corrections to a Catalog Published on October 2007

We notify corrections to the following catalogs, which were published in October 2007:

- A. Renesas Quick Reference Guide to Semiconductor Devices
Document No. REJ02A0003-0800 (printed and PDF editions)

- B. Renesas USB Device
Document No. REJ01B0005-0501 (PDF edition)

The corrections described below can be seen on the Web site at
http://www.renesas.com/tool_catalog
This site will be opened from December 20 on.

A. Corrections to "Renesas Quick Reference Guide to Semiconductor Devices"

Document No. REJ02A0003-0800

1. **Page 86**, body of the table; first row from the top in the Full-spec emulator column (in the SH7136 and SH7137 Group row)
Read (E200F) R0E0200F1EMU00 *13 *20 for (E200F) R0E0200F1EMU00 *13

2. **Ibid.**, notes under the table
Add the following note after *19:
*20. The E200F emulator can't evaluate I2C by using the system configuration with the Evaluation chip unit. In order to evaluate I2C, please install the H-UDI port connector (36-pin type) on the user system and use it with the system configuration without the Evaluation chip unit.

3. **Page 97**, "Adaptor board" column (second from the right) of the top table
Through the column exist three R0E000080AKCE00s. Read R0E00008AKCE00 for each of them: R0E000080AKCE00

4. Page 98, "Adaptor board" column (second from the right) of the table
Through the column exist three R0E000080AKCE00s. Corrections are the same as in Item 3 above.

5. Page 99, "Adaptor board" column (second from the right) of the table
Through the column exist three R0E000080AKCE00s. Corrections are the same as in Item 3 above.

6. Page 100, "Adaptor board" column (second from the right) of the top table
Through the column exists an R0E000080AKCE00. Correction is the same as in Item 3 above.

B. Correction to "Renesas USB Device"

Document No. REJ01B0005-0501

1. Page 32, "Programmer (Flash)" column (extreme right) of Development Tools for the H8SX, H8S Family's table
Through the column exist six R0E000080AKCE00s. Corrections are the same as in Item 3 of Section A above.

C. Related Information

We notified a correction to this catalog in the following RENESAS TOOL NEWS.

- RENESAS TOOL NEWS "Corrections to Catalogs Published in October 2007" issued on November 1, 2007.
- RENESAS TOOL NEWS "Corrections to Catalogs Published in October 2007" issued on April 16, 2008.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.