

RENESAS TOOL NEWS on December 16, 2005: RSO-R0C30800PMW00_2-051216D

A Note on Using the M32C Compact Emulator Debugger V.1.00 Release 00

Please take note of the following problem in using the M32C compact emulator debugger V.1.00 Release 00:

On changing the work area used by the compact emulator

1. Product Concerned

M32C compact emulator debugger V.1.00 Release 00

2. Description

You are unable to type anything in the Debug Monitor Bank Address edit box, which appears on-screen when clicking the Emulation Memory tab of the Emem dialog box.* So no changes can be made to the work area that the emulator uses.

* In the High-performance Embedded Workshop, if you switch a session to the one during which the debugger is used, or the Connect command is selected from the Debug menu, the Init dialog box appears. Clicking the OK button in this dialog box opens the Emem dialog box.

3. Solution

This problem has been resolved in the M32C compact emulator debugger V.1.00 Release 01. So download the installer of the V.1.00 Release 01 from Download site and then install it.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

 $\ @\ 2010\mbox{-}2016$ Renesas Electronics Corporation. All rights reserved.