

RENESAS TOOL NEWS on December 1, 2007: 071201/tn2

A Note on Using the Real-Time OS --HI1000/4 V.1.05 Release 00-- for the H8SX and H8S Families of MCUs

Please take note of the following problem in using the real-time OS-- HI1000/4 V.1.05 Release 00--for the H8SX and H8S families of MCUs:

- With selecting the product's release note among the Start menu of Windows (R)
-

1. Product and Version Concerned

HI1000/4 V.1.05 Release 00

2. Description

When you select the product's release note among the Start menu of Windows (R), the Missing Shortcut dialog box may open, and you are not able to open the release note.

3. Condition

This problem occurs if you select the release note among the Start menu of Windows (R) for the first time after installing the product.

4. Solution

Press the Browse button in the Missing Shortcut dialog box; then select HI1000_4_10500_REL_071101_E_.pdf in the ¥Manuals¥english folder, which you will find under the folder where you have installed HI1000/4.

If you open the release note once such a way, thereafter you can open the release note by selecting it among the Start menu of Windows (R).

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.