

[Notes]

R20TS0570EJ0100

Rev.1.00

Apr.16.2020

RX Family TSIP(Trusted Secure IP) Module Firmware Integration Technology

Outline

When using the product in the title, note the following point.

1. SSL/TLS cooperation function

1. SSL/TLS Cooperation Function

1.1 Applicable Products

RX Family TSIP(Trusted Secure IP) Module Firmware Integration Technology V1.08 or later.

1.2 Applicable Devices

RX Family:

RX65N/RX651, RX66N, RX72M, and RX72N groups

1.3 Details and Conditions

The following cipher suite cannot be used with the SSL / TLS cooperation function.

- TLS_ECDHE_ECDSA_WITH_AES_128_CBC_SHA256
- TLS_ECDHE_ECDSA_WITH_AES_128_GCM_SHA256

When the above cipher suite is specified in the SSL/TLS cooperation API, signature verification will not be performed correctly, and the following error message will appear.

- TSIP_ERR_FAIL

1.4 Workaround

There is currently no workaround for this problem.

1.5 Schedule for Fixing the Problem

This problem will be fixed in a later version.

Revision History

Rev.	Date	Description	
		Page	Summary
1.00	Apr.16.20	-	First Release

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URLs in the Tool News also may be subject to change or become invalid without prior notice.

Corporate Headquarters

TOYOSU FORESIA, 3-2-24 Toyosu,
Koto-ku, Tokyo 135-0061, Japan
www.renesas.com

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

Contact information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit:
www.renesas.com/contact/