

RENESAS TOOL NEWS on August 07, 2015: 150807/tn6

Device Information (Managed by CS+) for RX Family Revised to V1.09.00

We are revising the device information file (managed by CS+) for the RX family of MCUs and accordingly will change the version number from 1.08.00 to 1.09.00.

1. Product and Versions to Be Updated

- (1) Device information file managed by CS+ for the RX family of MCUs
(CS+ Device Information for RX) V1.08.00 or earlier
- (2) Device information file managed by CubeSuite+ for the RX family of MCUs
(CubeSuite+ DevInfo_RX) V1.03.00 or earlier

Check your version number of "CS+ Device Information for RX" or "CubeSuite+ DevInfo_RX" with reference to the procedure described under the heading "Components" at the URL below.

https://www.renesas.com/cs+_ver

2. Descriptions of Revision

(1) Addition of Supported MCUs

The following MCUs will be added to the supported line.

- RX230 group

R5F52305AxFL, R5F52305AxFM, R5F52305AxFP, R5F52305AxLA,
R5F52305AxLF, R5F52305AxND, R5F52305AxNE,
R5F52306AxFL, R5F52306AxFM, R5F52306AxFP, R5F52306AxLA,
R5F52306AxLF, R5F52306AxND, and R5F52306AxNE

- RX231 group

R5F52315AxFL, R5F52315AxFM, R5F52315AxFP, R5F52315AxLA,
R5F52315AxND, R5F52315AxNE,
R5F52316AxFL, R5F52316AxFM, R5F52316AxFP, R5F52316AxLA,
R5F52316AxND, R5F52316AxNE,
R5F52317AxFL, R5F52317AxFM, R5F52317AxFP, R5F52317AxLA,

R5F52317AxND, R5F52317AxNE,
R5F52318AxFL, R5F52318AxFM, R5F52318AxFP, R5F52318AxLA,
R5F52318AxND, R5F52318AxNE,
R5F52317BxFL, R5F52317BxFM, R5F52317BxFP, R5F52317BxLA,
R5F52317BxND, R5F52317BxNE,
R5F52318BxFL, R5F52318BxFM, R5F52318BxFP, R5F52318BxLA,
R5F52318BxND, R5F52318BxNE
R5F52315CxFL, R5F52315CxFM, R5F52315CxFP, R5F52315CxLA,
R5F52315CxLF, R5F52315CxND, R5F52315CxNE,
R5F52316CxFL, R5F52316CxFM, R5F52316CxFP, R5F52316CxLA,
R5F52316CxLF, R5F52316CxND, and R5F52316CxNE

(2) Correction to Device Information

I/O header file for the C language and the register information displayed in IOR panel will be updated for the group of MCUs listed below.

- RX23T group

3. Updating Your Product

Online updating is available free of charge.

To update either your commercial edition or evaluation edition of CS+, use either of the following methods.

3.1 For CS+ V3.00.00 or Later

To update your program, use either of the following methods:

(1) On the "Start" menu, select "Programs" and then "Renesas Electronics CS+" to start the Update Manager.

This service will be available from August 7.

Note:

If your CS+ has been launched with rapid startup enabled, exit the CS+ once, and then run the Update Manager.

If the CS+ is resident in the notification area of Windows (system tray) due to rapid startup, an error occurs and produces the following message:

M0120001

Installation is suspended because "CubeSuiteW+.exe" is running.
It will be resumed next time you start the tool.

(2) Download and install V1.09.00 of the device information file managed by CS+ for the RX family of MCUs from the following URL.

The program will be available from August 7.

https://www.renesas.com/cs+_download

3.2 For CubeSuite+ V2.02.01 and Earlier Versions

Please download and install the evaluation edition of CS+ V3.01.00 from the following URL.

https://www.renesas.com/cs+_download

Then, update your program by using the method in 3.1 (1) or (2) above.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.