

H8S/Tiny E100 Emulator Software Published

We have published H8S/Tiny E100 Emulator Software V.1.00 Release 00. The emulator software is included with the R0E420000MCU00 MCU unit.

1. Outline

H8S/Tiny E100 Emulator Software is used in combination with the E100 emulator and the R0E420000MCU00 MCU unit to evaluate and debug systems designed with MCUs of the H8S/Tiny series. This emulator software product is included with the R0E420000MCU00 MCU unit; you cannot purchase it alone.

The R0E420000MCU00 is the MCU unit for the H8S/Tiny MCU series, which has been released on February 16, 2010. For details of this MCU unit, see RENESAS TOOL NEWS Document No. 100216/tn2, published on February 16, 2010. This item of news is also accessible on and after February 19 at:

<https://www.renesas.com/search/keyword-search.html#genre=document&q=100216tn2>

2. Features

Main features of the product are as follows:

- (1) User-friendly GUI (graphical user interface)
- (2) Quick, easy operations by dragging and dropping
- (3) Fundamental debugging capabilities including source-level debugging in C and assembly languages
- (4) Real-time RAM monitoring
- (5) High-performance debugging capabilities such as real-time tracing, real-time profiling, coverage measurement, and time measurement
- (6) USB (USB 2.0 High-speed) supported
- (7) Online help in HTML

For details of those features, go to:

<https://www.renesas.com/products/software-tools/tools/emulator/e100--r0e420000mcu00.html>

This Web site is opened from February 19.
The above URL is one of our global sites.

3. The Contents of the Product

H8S/Tiny E100 Emulator Software V.1.00 Release 00 consists of the following components:

- (1) H8S/Tiny E100 Emulator Debugger V.1.00.00
- (2) High-performance Embedded Workshop V.4.06.00
- (3) AutoUpdate Utility V.1.05.00

4. Host System Requirements

Computer: IBM PC/AT or compatible

OS: Windows Vista(R), Windows(R) XP, or Windows(R) 2000

NOTICE: The 64-bit editions of Windows Vista(R) and Windows(R) XP excluded.

5. Notices

- If you install H8S/Tiny E100 Emulator Software V.1.00 Release 00 in a development system where High-performance Embedded Workshop V.4.05.01 or earlier resides, it will be updated to V.4.06.00.
- H8S/Tiny E100 Emulator Software V.1.00 Release 00 can not work with the WS products (working samples) of R0E420000MCU00 MCU unit.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.