

RENESAS TOOL NEWS on November 16, 2004: RSO-E8-041116D

The Software Product for the E8 Emulator Revised to V.1.02 Release 00

We have revised the software product for the E8 on-chip debugging emulator from V.1.01 Release 00 to V.1.02 Release 00.

1. Description

The software product supports the R8C/10, R8C/11, R8C/12, and R8C/13 groups of MCUs in addition. So the total of 24 types of MCU are supported, which are shown below.

R5F21102, R5F21103, R5F21104, R5F21112, R5F21113, R5F21114, R5F21122, R5F21123, R5F21124, R5F21132, R5F21133, R5F21134, R5F21142, R5F21143, R5F21144, R5F21152, R5F21153, R5F21154, R5F21162, R5F21163, R5F21164, R5F21172, R5F21173, and R5F21174

2. How to Revise Your Product

On-line revision is available free of charge. Please download the Update program of the revised product.

E8 emulator software V.1.02 Release 00 has a problem in its firmware. We have revised the E8 emulator software from V.1.02 Release 00 to V.1.02 Release 01. For details, see [RENESAS TOOL NEWS "The E8 Emulator Software Revised to V.1.02 Release 01" issued on December 22, 2004.](#)

3. Notices

- (1) If applied to the High-performance Embedded Workshop V.3.01.08 or earlier, the update program updates the High-performance Embedded Workshop to its V.3.01.08.
- (2) The update program does not update any of the tool chains except the High-performance Embedded Workshop.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be

included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.