

---

[Upgrade to revision]

R20TS0323EJ0100

Rev.1.00

Jul. 16, 2018

## CS+ Code Generator for RH850, AP4 Coding Assistance Tool for RH850

---

### Outline

The products in the title will be revised and their version numbers will be changed as follows.

- (1) CS+ Code Generator for RH850: From V1.03.00 to V1.04.00
- (2) AP4 Coding Assistance Tool for RH850: From V1.04.00 to V1.05.00

### 1. Products and Versions to Be Updated

- All revisions up to V1.03.00 of CS+ Code Generator for RH850
- All revisions up to V1.04.00 of AP4 Coding Assistance Tool for RH850

### 2. Items Revised

The major revision points are explained in section 2.1. Refer to the following Release Notes for details.

- CS+ Code Generator for RH850  
CS+ Code Generator for RH850 V1.04.00 Release Note  
This document will be released on July 20.  
<https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ut4349>
- AP4 Coding Assistance Tool for RH850  
AP4 for RH850 V1.05.00 Release Note  
This document will be released on July 20.  
<https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ut4356>

#### 2.1 Description of Modification

The problems regarding the following points have been fixed.

- (1) RENESAS TOOL NEWS, Document No. R20TS0274EJ0100

1. Interrupt Priority Settings

Applicable MCUs: RH850/F1K group

For details about the problem, refer to the following URL:

<https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ts0274>

## 3. Updating Your Product

The method of updating depends on the product you are using.

Refer to the following for details. Update of either product is free of charge.

### 3.1 Updating CS+ Code Generator for RH850

For the method of updating CS+, refer to section 4, "Updating Your Product" in RENESAS TOOL NEWS, Document No. R20TS0320EJ0100. This information will be available from July 20.

<https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ts0320>

### 3.2 Updating the AP4 Coding Assistance Tool for RH850

To install the program, download the installer from the URL below. This service will be available from July 20.

[https://www.renesas.com/applilet\\_download](https://www.renesas.com/applilet_download)

**Revision History**

| Rev. | Date          | Description |                      |
|------|---------------|-------------|----------------------|
|      |               | Page        | Summary              |
| 1.00 | Jul. 16, 2018 | -           | First edition issued |
|      |               |             |                      |

TOYOSU FORESIA, 3-2-24 Toyosu, Koto-ku, Tokyo 135-0061 Japan  
 Renesas Electronics Corporation

■Inquiry

<https://www.renesas.com/contact/>

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URLs in the Tool News also may be subject to change or become invalid without prior notice.

All trademarks and registered trademarks are the property of their respective owners.