

RENESAS TOOL NEWS on September 16, 2006: 060916/tn5

A Note on Updating the M32C Simulator Debugger

Please take note of the problem described below in updating the M32C simulator debugger from V.1.00.00 to V.1.02.00 using the AutoUpdate utility. (The M32C simulator debugger is used for the M32C/80, and M16C/80 MCU series.)

1. Problem

If the M32C simulator debugger has been installed together with the C compiler package--M3T-NC308WA V.5.40 Release 00--for the M32C series using the installer of the compiler package, it cannot be updated by the AutoUpdate utility with the error message "Unable to read update data" delivered.

2. Solution

If the above problem takes place, update your product by performing the following procedures:

- (1) Download the update program (file size: 68MB, ZIP) of the M32C simulator debugger.
- (2) Uncompress the downloaded ZIP file to obtain the executable file and then execute it.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.