# **RENESAS** Tool News

#### RENESAS TOOL NEWS on February 16, 2007: 070216/tn2

## A Note on Using the High-performance Embedded Workshop (IDE) --With Moving Workspaces, No. 3

Please take note of the following problem in using the High-performance Embedded Workshop:\*

• With moving workspaces, No. 3

\*This IDE is bundled with the software products such as compilers that it manages.

### **1. Product and Versions Concerned**

The High-performance Embedded Workshop V.3.01.02 through 4.02.00

To check for the version number of your High-performance Embedded Workshop, open the Help menu and select the About High-performance Embedded Workshop command.

#### 2. Description

If a workspace is moved to another directory and opened after you have customized (modified) the linking order of object files in the workspace, the customized linking order may be initialized (restored to alphabetical order).

#### 3. Condition

This problem occurs if source files that do not reside in the project directory are entered in a project.

#### 4. Workarounds

Avoid this problem in either of the following ways:

- (1) If you are using the workspace involved with the problem as it is, customize the linking order again.
- (2) If you are re-creating workspaces, place all the source files under the project directory and then create workspaces.

When all the source files are under the project directory, no linking orders are initialized if workspaces are moved to another directory.

#### 5. Schedule of Fixing the Problem

We will fix this problem when we revise the High-performance Embedded Workshop within the foreseeable future.

#### [Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

 $\ensuremath{\textcircled{\sc c}}$  2010-2016 Renesas Electronics Corporation. All rights reserved.