[Upgrade to revision]

Programming GUI "FP6 Terminal"

R20TS0367EJ0100 Rev.1.00 Nov. 27, 2018

for PG-FP6 Flash Memory Programmer V1.02.01

Outline

We have updated the "FP6 Terminal" programming GUI for the PG-FP6 flash memory programmer from V1.02.00 to V1.02.01. Refer to the URL below for an overview of the PG-FP6.

https://www.renesas.com/pg-fp6

1. Description of Update

1.1 Addition of Supported MCUs

Support has been added to the following MCUs.

(1) RX family

Group	Part number
RX66T	R5F566TA, R5F566TE

(2) RH850 family

Part number		
R7F701Z05A, R7F701Z06A, R7F701Z07A, R7F701Z11, R7F701Z12, R7F701Z12A		

(3) V850 family

Group	Part number
V850E2/DJ4	UPD70F3522, UPD70F3523, UPD70F3524, UPD70F3525, UPD70F3526
V850E2/DK4-H	UPD70F3529
V850E2/DN4-H	UPD70F3532
V850E2/DP4-H	UPD70F3535, UPD70F3536, UPD70F3537
V850E/DJ3	UPD70F3426, UPD70F3426A

1.2 Items Revised

The problem listed in the notes below has been corrected in this update.

- RENESAS TOOL NEWS, Document No. R20TS0339EJ0100
 - 2. Reset Vector Setting for V850ES/Dx2, V850ES/Fx2, and V850ES/Hx2

For details regarding this issue, refer to the URL below:

https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ts0339

2. Updating Your Product

You can update the FP6 Terminal free of charge. Download the installer from the following URL for an installation. The installer will be available on November 27.

https://www.renesas.com/pg-fp6#downloads

Revision History

		Description		
Rev.	Date	Page	Summary	
1.00	Nov. 27, 2018	-	First edition issued	

TOYOSU FORESIA, 3-2-24 Toyosu, Koto-ku, Tokyo 135-0061 Japan Renesas Electronics Corporation

■Inquiry

https://www.renesas.com/contact/

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URLs in the Tool News also may be subject to change or become invalid without prior notice.

All trademarks and registered trademarks are the property of their respective owners.

© 2018 Renesas Electronics Corporation. All rights reserved.

TS Colophon 2.1