



Integrated Device Technology, Inc.  
 2975 Stender Way, Santa Clara, CA - 95054  
 Phone #: (408) 727-6116 Fax #: (408) 727-2328

## PRODUCT DISCONTINUANCE NOTICE (PDN)

PDN #: _____S-0003_____	Last Buy Date: _____August 30, 2001_____
Issue Date: _____August 30,2000_____	Last Ship Date: _____November 30, 2001_____ (3 months after last buy date)

<b>PRODUCT(S) AFFECTED:</b> <i>(List Replacement Part #(s), if any)</i>	<b>ATTACHMENT</b> <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO																		
<table style="width: 100%; border: none;"> <thead> <tr> <th style="text-align: left; border-bottom: 1px solid black;"><u>IDT P/N</u></th> <th style="text-align: left; border-bottom: 1px solid black;"><u>REPLACEMENT P/N</u></th> </tr> </thead> <tbody> <tr><td>71V016S15Y</td><td>71V016SA15Y</td></tr> <tr><td>71V016S15YI</td><td>71V016SA15YI</td></tr> <tr><td>71V016S20Y</td><td>71V016SA20Y</td></tr> <tr><td>71V016S20YI</td><td>71V016SA20YI</td></tr> <tr><td>71V016S15PH</td><td>71V016SA15PH</td></tr> <tr><td>71V016S15PHI</td><td>71V016SA15PHI</td></tr> <tr><td>71V016S20PH</td><td>71V016SA20PH</td></tr> <tr><td>71V016S20PHI</td><td>71V016SA20PH</td></tr> </tbody> </table>	<u>IDT P/N</u>	<u>REPLACEMENT P/N</u>	71V016S15Y	71V016SA15Y	71V016S15YI	71V016SA15YI	71V016S20Y	71V016SA20Y	71V016S20YI	71V016SA20YI	71V016S15PH	71V016SA15PH	71V016S15PHI	71V016SA15PHI	71V016S20PH	71V016SA20PH	71V016S20PHI	71V016SA20PH	
<u>IDT P/N</u>	<u>REPLACEMENT P/N</u>																		
71V016S15Y	71V016SA15Y																		
71V016S15YI	71V016SA15YI																		
71V016S20Y	71V016SA20Y																		
71V016S20YI	71V016SA20YI																		
71V016S15PH	71V016SA15PH																		
71V016S15PHI	71V016SA15PHI																		
71V016S20PH	71V016SA20PH																		
71V016S20PHI	71V016SA20PH																		

<b>REASON FOR DISCONTINUANCE:</b>  <input type="checkbox"/> Replace slower speed with faster speed offerings  <input type="checkbox"/> Obsolete Fab Technology / Process  <input type="checkbox"/> Obsolete Assembly Technology / Process  <input type="checkbox"/> Obsolete Package / Material  <input type="checkbox"/> Declined Market	<input checked="" type="checkbox"/> Other: IDT is consolidating its specifications to simplify its materials management options.
---	--

**CUSTOMER NOTIFICATION:**  
 As a result of discontinuance reason(s) listed above, IDT has decided to discontinue certain products and notify you through this Product Discontinuance Notice (PDN). We recommend that you check detailed specifications before converting to equivalent devices offered. Please use acknowledgment below or E-Mail to request additional information.

*If you have any questions, please feel free to contact your local IDT distributor or sales representative.*

Customer: _____	E-Mail Address: _____
Name/Date: _____	Phone #: _____
Title: _____	Fax #: _____

**CUSTOMER COMMENTS:** \_\_\_\_\_

**IDT ACKNOWLEDGEMENT:**

Received By: \_\_\_\_\_ Date: \_\_\_\_\_